

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other Instructions on reverse side)

Form approved.
Budget Bureau No. 42-11421.

5. LEASE DESIGNATION AND SERIAL NO.

LC-030556B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Continental Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 460, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

990' FNL & 1650' FEL of Section 18,
T-23S, R-37E, Lea County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DZ, RT, CR, etc.)

3349 DF

7. UNIT AGREEMENT NAME

NMFU

8. FARM OR LEASE NAME

Stevens B-18

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Jalmit Gas

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 18, T-23S, R-37E

12. COUNTY OR PARISH 13. STATE

Lea

New Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The well will not produce gas in sufficient quantity to be commercial. The possibility of recompletion is not feasible.

Procedure to be followed in plugging well.

1. Pull tubing.
2. Spot 50 sacks cement over perf. interval 2771' - 3304'.
3. Spot 10 sacks surface plug.
4. Erect dry hole marker and restore location to original condition.

1011' with 10' mud between plugs.

ILLEGIBLE

18. I hereby certify that the foregoing is true and correct

SIGNED

(This space for Federal or State office use)

Administrative Section Chief

TITLE

DATE

10-21-69

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

USGS 5 File

*See Instructions on Reverse Side

