				1 57	<b>39</b> €,		
Form 9-331 (May 1963)		TO STATES	SUBMIT IN TRIPLI	™E• re-	Form appro	ved. eau No. 42–R1424.	
•	DEPARTMEN.	OF THE INTERI	OR verse side)	5. LEAS	E DESIGNATION	N AND SERIAL NO.	
	GEOLO	GICAL SURVEY		LC	-030187		
	TIMPDY MOTICES	6. IF IN	6. IF INDIAN, ALLOTTEE OR TRIBE NAME				
	SUNDRY NOTICES A			į			
(170 HOL USA	e this form for proposals to di Use "APPLICATION F	OR PERMIT—" for such pr	oposals.)				
1.			·	7. UNIT	AGREEMENT N	AME	
OIL G	ELL OTHER						
2. NAME OF OPERA	FOR	8. FARM	8. FARM OR LEASE NAME				
Gulf 011 0	Corporation	l c.	C. E. LaMunyon				
3. ADDRESS OF OPERATOR				9. WELI			
Box 670. F	lobbs, New Mexico	38240		8			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*				10. FIE	LD AND POOL,	OR WILDCAT	
At surface	See also space 17 below.) At surface			Te	Teague Simpson		
		<b>1</b>		11. SEC	., T., R., M., OR URVEY OR ARE	BLK. AND	
FSI. & 1980	FWL, Section 22,	23-S. 37-E	J. S. Gherry	- 1			
101 4 2,00	,,	<b>,</b>	HORRS II I I I I I	Se	c 22, 23	3-S, 37-E	
14. PERMIT NO.	15. Et	EVATIONS (Show whether DF,	RT, GR, etc.)	12. cou	NTY OR PARIS	H 13. STATE	
		3	287' GL	Le	a	New MEXIC	
16.	CL -1 A	Dan Ta Indiania N	ature of Notice, Report,	or Other De	.t.		
10.	Cneck Approprie	te box to indicate 14					
	NOTICE OF INTENTION TO	<b>:</b>	SUI	BSEQUENT REPO	RT OF:		
TEST WATER S	HUT-OFF PULL OR	ALTER CASING	WATER SHUT-OFF		REPAIRING	WELL	
FRACTURE TREA	MULTIPLI	E COMPLETE	FRACTURE TREATMENT		ALTERING	CASING	
SHOOT OR ACID	IZE ABANDON	•	SHOOTING OR ACIDIZING		ABANDONM	ENT*	
REPAIR WELL	CHANGE	PLANS	(Other)				
(Other) Ahar	nd Teague Simpson	& Comp in Montos	A (Note: Report re	sults of multi-	ple completion ort and Log f	n on Well	
17	SED OR COMPLETED OPERATIONS	(Clearly state all pertinent	details and give pertinent d	lates including	estimated de	ate of starting any	
	•						
B' PB.							
	er and injection to	whine Sat CI I	ID at approvimately	. 0100'	and can a	with 351	
rull backe	st and injection t	anang. Set of t	n at approximater	y Jivo c	mu cap v	WILL JJ	

cement to 9065', abandoning Teague Simpson open hole interval 9265' to 9433'. Perforate the Montoya zone in 7" casing with 2, 1/2" JHPF in the approximate interval 8630' to 8680'. Run treating equipment and treat new perforations with 3000 gallons of 15% NE acid. Pull treating equipment. Run packer and 2-3/8" tubing. Set packer at approximately 8600' and return well to production.

		·
8. I hereby certify that the foregoing is true and correct SIGNED D, T, Blillim	TITLE	Area Engineer VEP DATE April 14, 1976
(This space for Federal or State office use)		MENDE
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	APR 1 9 1976
		ARTHUR R. BROWN  ARTHUR R. BROWN  Ons on Reverse Side DISTRICT ENCINEER
*S	ee Instructio	ons on Reverse Side 15 The