	IENT OF THE INTE EOLOGICAL SURVEY	KIOR verse side)	re- 5. LEASE DESIGNATIO NM-27721	N AND SERIAL NO.
			6. IF INDIAN, ALLOTT	EE OR TRIBE NAME
SUNDRY NOII (Do not use this form for propose Use "APPLICA"	CES AND REPORTS	g back to a different reservoir.		
Use "APPLICA'	TION FOF. PERMIT—" for suc	h proposals.)	7. UNIT AGREEMENT	NAME
OIL CAS OTHER		REGEIVE	Myers Langli	
NAME OF OPERATOR Getty Oil Company		MAY 1 5 1978	8. FARM OR LEASE N Myers Langli	
ADDRESS OF OPERATOR P.O. Box 730 Hobbs, New	Mexico 88240	U 5. GEOLOGICAL SURV	9. WELL NO.	
LOCATION OF WELL (Report location clo See also space 17 below.)	early and in accordance with a	any State Regainements MEXICO		
At surface			Langlie Matt	
Unit letter D, 660' FNL	. & 660' FWL Section	on 29-T23S-R37E	SURVEY OR AR	EA.
			Sec. 29-T23S	
4. PERMIT NO.	15. ELEVATIONS (Show whethe 3309' DF	r DF, RT, GR, etc.)	12. COUNTY OF PARIS	SH 13. STATE N.M.
	1			· · · · · · · · · · · · · · · · · · ·
6. Check Ap	propriate Box To Indicate	e Nature of Notice, Report, a		-
NOTICE OF INTEN	TION TO:	SUB	SEQUENT REPORT OF:	· ·
	ULL OR ALTER CASING	WATER SHUT-OFF	BEPAIRING	[]
	IULTIPLE COMPLETE	FRACTURE TREATMENT SHOOTING OR ACIDIZING	ALTERING	
	HANGE PLANS	(Other)	······	
(Other) Return to produc 7. DESCRIBE PROPOSED OR COMPLETED OPE: proposed work. If well is directio		Completion or Reco	sults of multiple completio ompletion Report and Log	form.)
s a Jalmat gas well. Gul	If has elected to	any's La Munyon Feder abandon the Jalmat an Mattix. The workover	ral No. 4. It is nd turn the well	over to th
s a Jalmat gas well. Gul nit for operation of the 1) Rig up pulling unit. 2) Install BOP and pull 3) Squeeze Jalmat perfor 4) WOC 24 hrs. 5) Drill out cement and 6) Drill out CIBP @ 3300 7) Run Dual Lateralog an 8) Acidize Langlie Matt	If has elected to e unitized Langlie tubing. rations 2 <b>7</b> 72'-3103 test squeeze. D' and clean out o nd Compensated Neu ix open hole 3479'	abandon the Jalmat an Mattix. The workover ' with 300 sacks. pen hole 3479'-3750'. tron Density Log TD-3 3750' with 3000 gallo	ral No. 4. It is nd turn the well r procedure is a 2200'. ons 15% acid.	over to th s follows:
s a Jalmat gas well. Gul nit for operation of the 1) Rig up pulling unit. 2) Install BOP and pull 3) Squeeze Jalmat perfor 4) WOC 24 hrs. 5) Drill out cement and 6) Drill out CIBP @ 3300 7) Run Dual Lateralog an 8) Acidize Langlie Matt	If has elected to e unitized Langlie tubing. rations 2 <b>7</b> 72'-3103 test squeeze. D' and clean out o nd Compensated Neu ix open hole 3479'	abandon the Jalmat an Mattix. The workover ' with 300 sacks. pen hole 3479'-3750'. tron Density Log TD-3 3750' with 3000 gallo	ral No. 4. It is nd turn the well r procedure is a 2200'. ons 15% acid.	over to th s follows:
<pre>s a Jalmat gas well. Gul nit for operation of the 1) Rig up pulling unit. 2) Install BOP and pull 3) Squeeze Jalmat perfor 4) WOC 24 hrs. 5) Drill out cement and 6) Drill out CIBP @ 3300 7) Run Dual Lateralog an 8) Acidize Langlie Matt</pre>	If has elected to e unitized Langlie tubing. rations 2 <b>7</b> 72'-3103 test squeeze. D' and clean out o nd Compensated Neu ix open hole 3479'	abandon the Jalmat an Mattix. The workover ' with 300 sacks. pen hole 3479'-3750'. tron Density Log TD-3 3750' with 3000 gallo	ral No. 4. It is nd turn the well r procedure is a 2200'. ons 15% acid.	over to th s follows:
s a Jalmat gas well. Gul nit for operation of the 1) Rig up pulling unit. 2) Install BOP and pull 3) Squeeze Jalmat perfor 4) WOC 24 hrs. 5) Drill out cement and 6) Drill out CIBP @ 3300 7) Run Dual Lateralog an 8) Acidize Langlie Matt	If has elected to e unitized Langlie tubing. rations 2 <b>7</b> 72'-3103 test squeeze. D' and clean out o nd Compensated Neu ix open hole 3479'	abandon the Jalmat an Mattix. The workover ' with 300 sacks. pen hole 3479'-3750'. tron Density Log TD-3 3750' with 3000 gallo	ral No. 4. It is nd turn the well r procedure is a 2200'. ons 15% acid.	over to th s follows:
s a Jalmat gas well. Gul nit for operation of the 1) Rig up pulling unit. 2) Install BOP and pull 3) Squeeze Jalmat perfor 4) WOC 24 hrs. 5) Drill out cement and 6) Drill out CIBP 0 3300 7) Run Dual Lateralog an 8) Acidize Langlie Matt	If has elected to e unitized Langlie tubing. rations 2 <b>7</b> 72'-3103 test squeeze. D' and clean out o nd Compensated Neu ix open hole 3479'	abandon the Jalmat an Mattix. The workover ' with 300 sacks. pen hole 3479'-3750'. tron Density Log TD-3 3750' with 3000 gallo	ral No. 4. It is nd turn the well r procedure is a 2200'. ons 15% acid.	over to th s follows:
as a Jalmat gas well. Gul nit for operation of the 1) Rig up pulling unit. 2) Install BOP and pull 3) Squeeze Jalmat perfor 4) WOC 24 hrs. 5) Drill out cement and 6) Drill out CIBP 0 3300 7) Run Dual Lateralog an 8) Acidize Langlie Matt	If has elected to e unitized Langlie tubing. rations 2 <b>7</b> 72'-3103 test squeeze. D' and clean out o nd Compensated Neu ix open hole 3479'	abandon the Jalmat an Mattix. The workover ' with 300 sacks. pen hole 3479'-3750'. tron Density Log TD-3 3750' with 3000 gallo	ral No. 4. It is nd turn the well r procedure is a 2200'. ons 15% acid.	over to th s follows:
a Jalmat gas well. Gul nit for operation of the 1) Rig up pulling unit. 2) Install BOP and pull 3) Squeeze Jalmat perfor 4) WOC 24 hrs. 5) Drill out cement and 6) Drill out CIBP @ 3300 7) Run Dual Lateralog an 8) Acidize Langlie Matt	If has elected to e unitized Langlie tubing. rations 2 <b>7</b> 72'-3103 test squeeze. D' and clean out o nd Compensated Neu ix open hole 3479'	abandon the Jalmat an Mattix. The workover ' with 300 sacks. pen hole 3479'-3750'. tron Density Log TD-3 3750' with 3000 gallo	ral No. 4. It is nd turn the well r procedure is a 2200'. ons 15% acid.	over to th s follows:
s a Jalmat gas well. Gul nit for operation of the 1) Rig up pulling unit. 2) Install BOP and pull 3) Squeeze Jalmat perfor 4) WOC 24 hrs. 5) Drill out cement and 6) Drill out CIBP @ 3300 7) Run Dual Lateralog an 8) Acidize Langlie Matt	If has elected to e unitized Langlie tubing. rations 2 <b>7</b> 72'-3103 test squeeze. D' and clean out o nd Compensated Neu ix open hole 3479'	abandon the Jalmat an Mattix. The workover ' with 300 sacks. pen hole 3479'-3750'. tron Density Log TD-3 3750' with 3000 gallo	ral No. 4. It is nd turn the well r procedure is a 2200'. ons 15% acid.	over to th s follows:
<ul> <li>a Jalmat gas well. Guinit for operation of the limit for operating operating operation.</li> </ul>	If has elected to e unitized Langlie tubing. rations 2772'-3103 test squeeze. D' and clean out o nd Compensated Neu ix open hole 3479' d pump.Install pum	abandon the Jalmat an Mattix. The workover ' with 300 sacks. tron Density Log TD-3 3750' with 3000 gallo ping equipment and pl	ral No. 4. It is nd turn the well r procedure is a 2200'. ons 15% acid.	over to th s follows: on.
s a Jalmat gas well. Gul nit for operation of the 1) Rig up pulling unit. 2) Install BOP and pull 3) Squeeze Jalmat perfor 4) WOC 24 hrs. 5) Drill out cement and 6) Drill out CIBP @ 3300 7) Run Dual Lateralog an 8) Acidize Langlie Matt 9) Run tubing, rods, and	If has elected to e unitized Langlie tubing. rations 2772'-3103 test squeeze. D' and clean out o nd Compensated Neu ix open hole 3479' d pump.Install pum	abandon the Jalmat an Mattix. The workover ' with 300 sacks. pen hole 3479'-3750'. tron Density Log TD-3 3750' with 3000 gallo	ral No. 4. It is nd turn the well r procedure is a 2200'. ons 15% acid.	over to th s follows:
Is a Jalmat gas well. Gul init for operation of the 1) Rig up pulling unit. 2) Install BOP and pull 3) Squeeze Jalmat perfor 4) WOC 24 hrs. 5) Drill out cement and 6) Drill out CIBP @ 3300 7) Run Dual Lateralog an 8) Acidize Langlie Matt 9) Run tubing, rods, and 18. Thereby ceighting medication Dale B. Grock	If has elected to e unitized Langlie tubing. rations 2772'-3103 test squeeze. D' and clean out o nd Compensated Neu ix open hole 3479' d pump.Install pum	abandon the Jalmat an Mattix. The workover ' with 300 sacks. tron Density Log TD-3 3750' with 3000 gallo ping equipment and pl	DATE	over to th s follows: on. 5-10-78
As a Jalmat gas well. Gul (1) Rig up pulling unit. (2) Install BOP and pull (3) Squeeze Jalmat perfor (4) WOC 24 hrs. (5) Drill out cement and (6) Drill out CIBP @ 3300 (7) Run Dual Lateralog and (8) Acidize Langlie Matt (9) Run tubing, rods, and 18. I hereby cetop is instruction (9) Run tubing, rods, and (9) Run tubing, rods, and (18. I hereby cetop is instruction (9) Run tubing, rods, and (19. Crock (This space for Federal or State officients) (19. Approved By	If has elected to e unitized Langlie tubing. rations 2772'-3103 test squeeze. D' and clean out o nd Compensated Neu ix open hole 3479' d pump.Install pum d pump.Install pum	abandon the Jalmat an Mattix. The workover ' with 300 sacks. tron Density Log TD-3 3750' with 3000 gallo ping equipment and pl	DATE	over to th s follows: on. 5-10-78
As a Jalmat gas well. Gul (1) Rig up pulling unit. (2) Install BOP and pull (3) Squeeze Jalmat perfor (4) WOC 24 hrs. (5) Drill out cement and (6) Drill out CIBP @ 3300 (7) Run Dual Lateralog and (8) Acidize Langlie Matt (9) Run tubing, rods, and 18. I hereby cetor federal or State official (This space for Federal or State official (This space for Federal or State official)	If has elected to e unitized Langlie tubing. rations 2772'-3103 test squeeze. D' and clean out o nd Compensated Neu ix open hole 3479' d pump.Install pum d pump.Install pum	abandon the Jalmat an Mattix. The workover ' with 300 sacks. tron Density Log TD-3 3750' with 3000 gallo ping equipment and pl	DATE	over to th s follows: on. 5-10-78
As a Jalmat gas well. Gul (1) Rig up pulling unit. (2) Install BOP and pull (3) Squeeze Jalmat perfor (4) WOC 24 hrs. (5) Drill out cement and (6) Drill out CIBP @ 3300 (7) Run Dual Lateralog and (8) Acidize Langlie Matt (9) Run tubing, rods, and 18. I hereby cetop is instruction (9) Run tubing, rods, and (9) Run tubing, rods, and (18. I hereby cetop is instruction (9) Run tubing, rods, and (19. Crock (This space for Federal or State officients) (19. Approved By	If has elected to e unitized Langlie tubing. rations 2772'-3103 test squeeze. D' and clean out o nd Compensated Neu ix open hole 3479' d pump.Install pum d pump.Install pum	abandon the Jalmat an Mattix. The workover ' with 300 sacks. tron Density Log TD-3 3750' with 3000 gallo ping equipment and pl	DATE	over to th s follows: on. 5-10-78 <b>)VED</b> 1978