		Mexico		Form C-1
Office District I	Energy, Minerals and N	atural Resources		Revised March 25, 19
1625 N. French Dr., Hobbs, NM 87240			WELL API NO.	5- 10888
District II 811 South First, Artesia, NM 87210	OIL CONSERVATI		5. Indicate Type of	
District III	2040 South I		STATE	FEE 🔀
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NN	4 87505		
2040 South Pacheco, Santa Fe, NM 87505			6. State Oil & Gas I 8910138170 -	Lease No.
(DO NOT USE THIS FORM FOR PROPC	ES AND REPORTS ON W SALS TO DRILL OR TO DEEPE	EN OR PLUG BACK TO A	T	nit Agreement Name:
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.) 1. Type of Well:		-101) FOR SUCH	Myers Langlie Mat	ttix Unit
Oil Well 🔀 Gas Well 🗌	Other		0.111.11.11	
2. Name of Operator		100.00	8. Well No. 31	
OXY USA WTP Limited Partners	nip	19246	9. Pool name or Wil	deat
3. Address of Operator P.O. Box 50250 Midland, TX	79710-0250		Langlie Mattix 76	
4. Well Location				
	150 feet from the <u>So</u>	uth line and 1	feet from	the west lir
Section <b>30</b>	Township 23	Range 37	NMPM	County Lea
	10. Elevation (Show wheth	her DR, RKB, RT, GR, et		
11. Check A	ppropriate Box to Indic			
NOTICE OF INTE			SEQUENT REPO	
	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
	CHANGE PLANS [			PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE [ COMPLETION	CASING TEST AND CEMENT JOB		
OTHER:	٢		Status	
12. Describe Proposed or Complete	d Operations (Clearly state a	Il pertinent details, and g	ive pertinent dates, inc	luding estimated date
<ul> <li>12. Describe Proposed or Complete of starting any proposed work). or recompilation.</li> <li>OXY USA WTP LP requests to TD-<u>3759</u> PBTD-<u>34</u></li> <li>1. Notify <u>PLM</u>/NMOCD of cas</li> <li>2. RU pump truck <u>129.03</u></li> <li>to <u>560</u> # for 30 m</li> </ul>	SEE RULE 1103. For Multi to temporarily abandon th Sing integrity test 24hr , circulate well with nin.	ple Completions: Attach nis well for possible <u>3-3156' Pkr</u> /CI rs in advance. treated water, press	wellbore diagram of p e future use. BP- <u>3488</u>	Luding estimated date proposed completion
<ul> <li>12. Describe Proposed or Complete of starting any proposed work). or recompilation.</li> <li>OXY USA WTP LP requests to TD-<u>3759</u> PBTD-<u>34</u></li> <li>1. Notify <del>DLM</del>/NMOCD of cas</li> <li>2. RU pump truck 129.03</li> </ul>	SEE RULE 1103. For Multi to temporarily abandon the Sing integrity test 24hr c, circulate well with min. This Approval Abandonment E	ple Completions: Attach his well for possible <b>3-3151</b> Pkr/CI rs in advance. treated water, press <b>1 of Temporary</b> <b>Expires</b>	wellbore diagram of p e future use. BP- $3438'$ sure test casing 3/4/08	broposed completion
<ul> <li>12. Describe Proposed or Complete of starting any proposed work). or recompilation.</li> <li>OXY USA WTP LP requests to TD-<u>3759</u> PBTD-<u>34</u></li> <li>1. Notify <del>BLM</del>/NMOCD of case 2. RU pump truck <u>129.03</u> to <u>560</u> # for 30 m</li> </ul>	SEE RULE 1103. For Multi to temporarily abandon the Sing integrity test 24hr c, circulate well with min. This Approval Abandonment E	ple Completions: Attach his well for possible <b>3-3151' Pkr</b> /CI rs in advance. treated water, press <b>1 of Temporary</b> <b>Expires</b>	wellbore diagram of p e future use. BP- $3438'$ sure test casing 3/4/08	ATE <u>zizso3</u>
<ul> <li>12. Describe Proposed or Complete of starting any proposed work). or recompilation.</li> <li>OXY USA WTP LP requests to TD-<u>3759</u> PBTD-<u>34</u></li> <li>1. Notify <del>DLM</del>/NMOCD of case 2. RU pump truck <u>129.03</u> to <u>560</u> # for 30 membereby certify that the information above</li> </ul>	SEE RULE 1103. For Multi to temporarily abandon the sing integrity test 24hr b, circulate well with nin. This Approval Abandonment E	ple Completions: Attach his well for possible <u>3-3151</u> Pkr/CI rs in advance. treated water, press of Temporary xpires of my knowledge and belie ITLE Sr. Regulatory	wellbore diagram of p e future use. BP- <u>3488'</u> sure test casing <u>3/4/08</u> f. <u>Analyst</u> D. Telephon	broposed completion ATE z z 5 03 e No. 915-685-5717
<ul> <li>12. Describe Proposed or Complete of starting any proposed work). or recompilation.</li> <li>OXY USA WTP LP requests to TD-3759 PBTD-39</li> <li>1. Notify PLM/NMOCD of cas</li> <li>2. RU pump truck 129/03</li> <li>to 560 # for 30 members of the space for State use)</li> </ul>	SEE RULE 1103. For Multi to temporarily abandon the sing integrity test 24hr b, circulate well with nin. This Approval Abandonment E	ple Completions: Attach his well for possible <u>3-3151</u> Pkr/CI rs in advance. treated water, press of Temporary xpires of my knowledge and belie ITLE Sr. Regulatory	wellbore diagram of p e future use. BP- <u>3488'</u> sure test casing <u>3/4/08</u> f. <u>Analyst</u> D. Telephon	broposed completion ATE z z 5 03 e No. 915-685-5717
<ul> <li>12. Describe Proposed or Complete of starting any proposed work). or recompilation.</li> <li>OXY USA WTP LP requests to TD-<u>3759</u> PBTD-<u>39</u></li> <li>1. Notify <del>DLM</del>/NMOCD of case 2. RU pump truck <u>129.63</u></li> <li>to <u>560</u> # for 30 methods the set of the</li></ul>	SEE RULE 1103. For Multi to temporarily abandon the sing integrity test 24hr b, circulate well with nin. This Approval Abandonment E	ple Completions: Attach his well for possible <b>3-3151</b> Pkr/CI rs in advance. treated water, press <b>1 of Temporary</b> <b>Expires</b>	wellbore diagram of p e future use. BP- <u>3488'</u> sure test casing <u>3/4/08</u> f. <u>Analyst</u> D. Telephon	broposed completion ATE z z 5 03 e No. 915-685-5717