	~					
(May 1963) UNITED STATES DEPARTMENT OF THE INTERIOR Verse side)				son re-l_	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.	
GEOLOGICAL SURVEY					LC-054668 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTI (Do not use this form for propose Use "APPLICA"					5. IF INDIAN, ALLOY	TTEE OR TRIBE NAME
1. OIL XX GAS WELL XX WELL OTHER					7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Sun Exploration & Production Co.				2	8. FARM OR LEASE NAME	
3. ADDRESS OF OPERATOR					Farnsworth "4" 9. WELL NO.	
P.O. Box 1861 Midlar	id, Texas 797	702	0555	∇	5	
4. LOCATION OF WELL (Report location clearly and in accordance with the State requirements) See also space 17 below.) At surface					10. FIELD AND POOL, OR WILDCAT Langlie-Mattix 11. SEC., T., R., M., OB BLK, AND SUBVEY OR ABEA	
2310' FSL & 990' FWL,	Unit L	The l		<u> </u>		-26-S, R-37-E
14. PERMIT NO.	15. ELEVATIONS (Show 2997.2 DF		GEOLOCIONI MEX SWELL, NEV MEX		12. COUNTY OF PAR Lea	New Mexico
16. Check Ap	propriate Box To In				ner Data	
					UENT REPORT OF:	
TEST WATER SHUT-OFF	ULL OR ALTER CASING		WATER SHUT-OFF		REPAIRIN	IG WELL
	ULTIPLE COMPLETE		FRACTURE TREATM	ENT	ALTERIN	G CASING
SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING REPAIR WELL CHANGE PLANS (Other)					ABANDON	MENT*
(Other) Add Perfs & Stim		X	(NOTE : Repo	ort results of or Recompleti	multiple completi on Report and Log	on on Well
 DESCRIBE PROPOSED OR COMPLETED OPER proposed work. If well is direction nent to this work.) * 	ATIONS (Clearly state al	ll pertinent de rface locations	tails and give nortin	ont dates in	cluding estimated	data of stanting any
<pre>Due to response from an for 16 days. Average p To increase production stimulate. 1. MIRU workover rig. 2. POH w/ tbg. 3. GIH w/ 2~7/8" tbg., 2% KCL wtr. 4. POH w/ bit and scra 5. Rig up NL McCulloug A geologist will be 6. Perforate 3220-24', McCullough 4" Dyna Total holes -18. 7. Spot 20/40 sand acr 8. GIH w/ 2-7/8" tbg. from 3250-3163. Pul</pre>	roduction for it is recommer POH w/ rods ar bit, and scra per. h wireline. Ru on location t 3230-36', and Jet gun using oss lower perf and Baker RDG	the test ided to p id pump. aper. Cle un a gamm to correl i 3240-48 180 deg fs 3262-8 pkr to 3	ing period wa erf additiona Install BOP. an out hole a ray log w/ ate log. ' RA (From Gi phasing. Shoo 8' w/ dump ba 250'. Howco s	as 6 BOF al Lang to 3290 collar R-N log ot 1 SPF ailer. [spot 175	PD and 113 lie Mattix locator fro dated 3/29, . Gram cha Determine e: 5 gal 15% Mu	BWPD. pomosity and e hole w/ om 2400-3290. /58), w/ rge -22 xact top.
18. I hereby certify that the foregoing is	1	····				<u> </u>
SIGNED Maria L. H		<u>Sr.</u>	Acctg Assist	tant	DATE4/2	26/82
(This space for Federal of Fine of						<u> </u>
(Orig. Sgd.) PETER W APPROVED BY CONDITIONS OF APPROVAL, IF AN	TIT	LE			DATE	
APR 2	9 1982					
FOR JAMES A. DISTRICT SI	GILLHAM *See In s UPERVISOR	structions on	Reverse Side			

*



RECEIVED

APR 30 1982

,

(

9 3.0 **5** 3.00 (10 (10 4) Farnsworth "4" Procedure..

- 9. Halliburton acidize perfs 3220-48' in 2 equal stages with 3200 gals 15% MCA acid using TBA-110 (and TLC-80) to divert. Pump at 4-5 BPM. The estimated surface treating pressure is 1800psi. Acidize as follows. 15% MCA acid to contain 1 gal. HAI-50/1000 gals. acid and 30 gals. Morflo 11/1000 gals. acid.
- 10. Swab well. Report results.
- 11. If instructed by Midland office, rig up Halliburton and frac well with 50 quality frac fluid containing 10,000 gals. gelled 2% KCL wtr plus 10,000 gals liquid CO2 carrying 30,000# 20/40 sand. Frac down 2-7/8" tbg. at 18 BPM. The anticipated surface treating pressure is 2500 psi. Follow the procedure listed.
- 12. Let well unload naturally. Swab if necessary.
- 13. GIH w/ hydrostatic bailer on 2-7/8" tbg. Clean out hole to 3290'.
- 14. POH w/ tbg. and pkr.

Ņ

- 15. GIH w/ 2-3/8" tbg., 3/4" rods and l_{2}^{\pm} " plunger pump. Set seating nipple at 3200'. Tbg. bottom will be approximately 3231'.
- 16. Beam well and test. Pump 45" stroke at 12 SPM.

