

Form 3160-5
(July 1989)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVED
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on reverse
side)

BLM Roswell District
Modified Form No.
NMO60-3160-4

5. LEASE DESIGNATION AND SERIAL NO.

LC-030176A

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1. OIL WELL ☐ GAS WELL ☒ OTHER

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR
MERIDIAN OIL INC

8. FARM OR LEASE NAME

Cagle "B"

3. ADDRESS OF OPERATOR
P.O. Box 51810, Midland, TX 79710-1810

3a. AREA CODE & PHONE NO.
(915)688-6898

9. WELL NO.

2

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
M, 660' FSL & 660' FWL

10. FIELD AND POOL, OR WILDCAT
RHODES-YATES-7RV

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC 15, T26S, R37E

14. PERMIT NO.
30-025-0321600

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
2999' GR

12. COUNTY OR PARISH
LEA

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

☐
☐
☐
☐
☐

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

☐
☐
☒
☐
☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

☐
☐
☐
☐

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

☐
☐
☐
☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

NOTIFY BLM PRIOR TO COMMENCING PLUGGING OPERATIONS.

RIH, STING INTO CEMENT RETAINER @ 2972'. SQUEEZE OPEN HOLE UNDER RETAINER W/100 SX CL. C CMT. SPOT CEMENT PLUG @ 2655' - 2972' (55 SX). SPOT 57 BBL OF 9 PPG GELLED BRINE.

PERFORATE 4 SQUEEZE HOLES @ 1210'. SQUEEZE ANNULUS BY PUMPING 235 SX (40% EXCESS) CMT DOWN 7" CASING. USE CL. C CMT. DROP WIPER PLUG AND DISPLACE TO 1065' USING 41.5 BBL OF 9 PPG GELLED BRINE. TAG PLUG.

PULL UP TO 315' AND CIRC CMT TO SURFACE. CUT OFF CASING 3' BELOW GROUND LEVEL AND INSTALL P&A MARKER. CLEAR LOCATION.

18. I hereby certify that the foregoing is true and correct.

SIGNED

TITLE

REG. COMPLIANCE REP.

DATE

3/31/92

(This space for Federal or State official use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side