	• 1 to -		
NO. OF COPIES RECEIVED			
DISTRIBUTION			Form C-103
SANTA FE			Supersedes Old C-102 and C-103
FILE	NEW MEXICO OIL CONSERVATIO	ON COMMISSION	Effective 1-1-65
U.S.G.S.			
LAND OFFICE			5a. Indicate Type of Lease
OPERATOR			State XX Fee
			5. State Oil & Gas Lease No.
			B-1732
(00 NOT USE THIS FORM FOR USE "APPLI	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A D CATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSAL	IFFERENT RESERVOIR, LS.)	
OIL GAS			7. Unit Agreement Name
2. Name of Operator	OTHER.	West Do	
•		West Do	larhide Devonian Unit 8. Form or Lease Name
Gulf Oil Corporation			and a Loose Maine
3. Address of Operator			9. Well No.
Box 670, Hobbs, New Mexico 88240			1
			113
UNIT LETTER C 667 FEET FROM THE NORTH LINE AND 781 FEET FROM			10. Field and Pool, or Wildcat
•	FEET FROM THE LINE AN	DFEET FROM	Dollarhide Devonian
THE East	4 25 0	<u> </u>	\mathbf{v}
LINE, SEC	TION 4 TOWNSHIP 25-S RANG	GE NMPM.	
	15. Elevation (Show whether DF, RT, GI	D	
			12. County
16. Cl	3158' GL		Lea
Checi	Appropriate Box To Indicate Nature of	Notice, Report or Oth	er Data
NOTICE OF	INTENTION TO:	SUBSEQUENT	REPORT OF
]		
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL	WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE	DRILLING OPNS.	
PULL OR ALTER CASING	CHANGE PLANS CASING TE	ST AND CEMENT JOB	PLUG AND ABANDONMENT
Porforate bill			· · · · · · · · · · · · · · · · · · ·
OTHER Perforate highe	r and acidize.		
17. Describe Proposed or Completed			

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7965' TD.

Pull producing equipment. Run treating equipment and treat 6-1/2" open hole interval 7756' to 7965' with 1000 gallons of 28% NE acid. Flush with treated water. Swab and clean up. Pull treating equipment. Perforate upper Devonian zone in 7" casing with 4, 1/2" JHPR from 7739' to 7754'. Run treating equipment and treat new perforations with 1000 gallons of 28% NE acid. Swab and clean up. Pull treating equipment. Clean out to total depth 7965'. Run 2-3/8" tubing, rods and pump and return well to production.

		complete to the best of my knowledge and belief.	
gned,	Berlin	TITLE Area Engineer	DATE October 2, 1975
	Orig. Signed by		975
PROVED BY	John Runyan PROVAL, IF Geologist	TITLE	DATE