wo of control profiles			F C 100
NO. OF COPIES RECEIVED			Form C-103 Supersedes Old
DISTRIBUTION	NEW MEXICO OIL CONSERVA	TION COMMISSION	C-102 and C-103
SANTA FE		HON COMMISSION	Effective 1-1-65
FILE	9 371000	1136	5a. Indicate Type of Lease
U.S.G.S.	3-NMOCC	1 10	State Fee. 🗶
OPERATOR	l-File		5. State Oil & Gas Lease No.
OT ENATOR			
(DO NOT USE THIS FORM FOR	DRY NOTICES AND REPORTS ON WELL PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO CATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPI	A DIFFERENT RESERVOIR.	
l. OIL GAS	CATTON FOR FERMIT = TOOMS COTOTY FOR SUCH FROM	03AE3.)	7. Unit Agreement Name
WELL X WELL	OTHER-		S. Farm or Lease Name
2. Name of Operator	2		
Tidewater Oil Company 3. Address of Operator			L. M. Buffington B
	War Maria		3
Box 249, Hobbs	, New Mexico		10. Field and Pool, or Wildcat
	Country Country	33/	
UNIT LETTER	660 FEET FROM THE South LIN	E AND FEET FRO	JUSTIS ET LENOTESET
17	ction 19 township 25 S	ე (13	
THE WEST LINE, SE	ction township 25 5	RANGE NMP	(
	15. Elevation (Show whether DF, RY	T, GR, etc.)	12. County
	3030 RT		Jea ())))))
16. Chec	k Appropriate Box To Indicate Nature		Other Data
	FINTENTION TO:	•	NT REPORT OF:
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
PERFORM REMEDIAL WORK	PLUG AND ABANDON REME	EDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMN	MENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASIN	NG TEST AND CEMENT JOB	
	o.	THER	
OTHER			
17 Decering Dropound or Complete	Operations (Clearly state all pertinent details, an	nd give pertinent dates, includi	ng estimated date of starting any proposed
work) SEE RULE 1103.	Toperations (Greatly State att pertinent actains, un	a george person in daves, therear	ng continuous sales of starting any proposes
McKee zone is	dual oil well producing from t Justis McKee Unit Well #701.	The Elleaburger zon	ne has ceased
and complete h	increased water cut. It is puigher in the Ellenburger and re	eturn the well to f	flowing status.
	formed as follows: Pull tubing		
of 2-3/8" EU 8	R tubing open-ended with Baker	anchor seal assemb	oty. Set tubing
	ly 7840 and latch into Baker i		
	8" Hardy Griffin and test in he		
	bing. Tag bottom of 8-3/4" ho		
	plug on bottom. Pick up tubin		
	g. Lay another plug if cement		
	l" tubing. Perforate Ellenbur		1900-10 With
two jets snots	per foot. Swab and test, acid	arze ii necessary.	
18. I hereby certify that the informa	tion above is true and complete to the best of my k	nowledge and belief.	
Original Signal	gned By:		
SIGNED B. M. BRE		Engineer	DATE <u>8-3-66</u>
~			\$ 1