		O STATES		FORM APPROVED
(Jun	e 1990) DEPARTMENT (OF THE INTERIOR	N.M. Oil Cons. Divisio	Budget Bureau No. 1004-0135 Expires: March 31, 1993
	BUREAU OF LA	ND MANAGEMENT	P.O. Box 1980	5. Lease Designation and Serial No.
			Hobbs, NM 88241	NM-021422
	SUNDRY NOTICES AN	ND REPORTS ON N		6. If Indian, Allottee or Tribe Name
l	Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals			
	Use "APPLICATION FOR F	PERMIT—" for such p	roposals	7. If Unit or CA, Agreement Designation
	SUBMIT IN			ANTELOPE RIDGE UNIT
1	Type of Well		ANTELOI E RIDGE UNIT	
••	Oil Gas		ł	8. Well Name and No.
2.	Well Well Other			Antelope Ridge Unit #2
	CITATION OIL & GAS CORP.			9. API Well No.
	Address and Telephone No.	<u> </u>		30-025-20444
	8223 Willow Place South, Ste. 250, Houston	n, Texas 77070-5623	(713) 469-9664	10. Field and Pool, or Exploratory Area
	Location of Well (Footage, Sec., T., R., M., or Survey Descriptio			Antelope Ridge Morrow
	B Section 4, T24S, R34E, 660' FNL & 10	650' FEL		11. County or Parish, State
	,, _, _, ,			Lea County, New Mexico
12.	CHECK APPROPRIATE BOX(s) TO INDICATE NA	TURE OF NOTICE, REPO	RT. OR OTHER DATA
	TYPE OF SUBMISSION	,	TYPE OF ACTION	
<u> </u>	Notice of Intent	Aband	lonment	Change of Plans
			npletion	New Construction
	Subsequent Report		ng Back	Non-Routine Fracturing
			z Repair	Water Shut-Off
	Final Abandonment Notice		ng Casing	Conversion to Injection
	_	Other	Plug off Devonian and complete as single	Dispose Water
		producer		
		producer		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
13.	Describe Proposed or Completed Operations (Clearly state all p give subsurface locations and measured and true vertical depths	producer pertinent details, and give pertine	ent dates, including estimated date of starting ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
	give subsurface locations and measured and true vertical depths	producer pertinent details, and give pertine for all markers and zones pertin	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled,
13.	give subsurface locations and measured and true vertical depths See attached procedure to plug back the D	producer pertinent details, and give pertine for all markers and zones pertin	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled,
13.	give subsurface locations and measured and true vertical depths	producer pertinent details, and give pertine for all markers and zones pertin	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled,
13.	give subsurface locations and measured and true vertical depths See attached procedure to plug back the D	producer pertinent details, and give pertine for all markers and zones pertin	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled,
13.	give subsurface locations and measured and true vertical depths See attached procedure to plug back the D	producer pertinent details, and give pertine for all markers and zones pertin	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled,
13.	give subsurface locations and measured and true vertical depths See attached procedure to plug back the D	producer pertinent details, and give pertine for all markers and zones pertin	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled,
13.	give subsurface locations and measured and true vertical depths See attached procedure to plug back the D	producer pertinent details, and give pertine for all markers and zones pertin	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled,
13.	give subsurface locations and measured and true vertical depths See attached procedure to plug back the D	producer pertinent details, and give pertine for all markers and zones pertin	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled,
13.	give subsurface locations and measured and true vertical depths See attached procedure to plug back the D	producer pertinent details, and give pertine for all markers and zones pertin	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled,
13.	give subsurface locations and measured and true vertical depths See attached procedure to plug back the D	producer pertinent details, and give pertine for all markers and zones pertin	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled,
	give subsurface locations and measured and true vertical depths See attached procedure to plug back the D	producer pertinent details, and give pertine for all markers and zones pertin	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled,
-13.	give subsurface locations and measured and true vertical depths See attached procedure to plug back the D	producer pertinent details, and give pertine for all markers and zones pertin	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled,
	give subsurface locations and measured and true vertical depths See attached procedure to plug back the D	producer pertinent details, and give pertine for all markers and zones pertin	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled,
-13.	give subsurface locations and measured and true vertical depths See attached procedure to plug back the D	producer pertinent details, and give pertine for all markers and zones pertin	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled,
	give subsurface locations and measured and true vertical depths See attached procedure to plug back the D	producer pertinent details, and give pertine for all markers and zones pertin	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled,
-13.	give subsurface locations and measured and true vertical depths See attached procedure to plug back the D	producer pertinent details, and give pertine for all markers and zones pertin	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled,
13.	give subsurface locations and measured and true vertical depths See attached procedure to plug back the E in the existing Morrow formation.	producer pertinent details, and give pertine for all markers and zones pertin	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled,
	give subsurface locations and measured and true vertical depths See attached procedure to plug back the D in the existing Morrow formation.	producer pertinent details, and give pertine for all markers and zones pertine Devonian perforations	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled, didge #2 well as a single completion
	give subsurface locations and measured and true vertical depths See attached procedure to plug back the D in the existing Morrow formation.	producer pertinent details, and give pertine for all markers and zones pertine Devonian perforations	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled,
	give subsurface locations and measured and true vertical depths See attached procedure to plug back the D in the existing Morrow formation.	producer pertinent details, and give pertine for all markers and zones pertine Devonian perforations Title	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (any proposed work. If well is directionally drilled, (b) (a) (b) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c
	give subsurface locations and measured and true vertical depths See attached procedure to plug back the E in the existing Morrow formation.	producer pertinent details, and give pertine for all markers and zones pertine Devonian perforations Title	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ; any proposed work. If well is directionally drilled, didge #2 well as a single completion
	give subsurface locations and measured and true vertical depths See attached procedure to plug back the D in the existing Morrow formation.	producer pertinent details, and give pertine for all markers and zones pertine Devonian perforations Title	ent to this work.)*	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (any proposed work. If well is directionally drilled, (b) (a) (b) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

PROCEDURE

Notify BLM 48 hrs prior to workover of intent.

- 1. Dig work over pit & set 500 Bbl Frac tank. Load & PT 7 5/8" x 2 7/8" x 2 3/8" annulus to 1,000 psi using 8.7 ppg BW.
- Attempt to load both LT (2 7/8") & UT (2 3/8") tbg w/8.7 ppg BW. Capacity to perfs: (LT = 103 Bbls, UT = 119 Bbls)
- 3. MIRU PU. Unit needs to be strung up on 6 lines. Kill well w/8.7 ppg BW. Have full opening 2 3/8" & 2 7/8" TTW valves on rig floor.
- 4. Install type "H" BPV in UT (2 1/16" bore) & LT (2 9/16" bore) in CIW type "AP" thg hangers.
- 5. ND WHD. NU 11" 10M# x 11" 5M# spool & 5M# Hyd. BOP w/Blinds & offset 2 3/8" & 2 7/8" rams.
- 6. Remove BPV in both strings.
- PU 2 3/8" lift sub & remove UT tbg hanger. Work UT tbg & attempt to release Seal Assy f/parallel flow tube
 (a) 11,465' (String landed w/10pts compression). Mx Pull (80% Yld) = 78,000#. If successful, POH & LD 2
 3/8" 4.7# C-75 CS Hyd tbg. If unsuccessful, re-land UT tbg in tbg head.
- PU 2 7/8" lift sub & remove 2 7/8" LT tbg hanger. RU WL & run 1 7/16" Free Point on 2 7/8" LT 6.5# C-75 CS Hyd tbg. Evaluate FP to Chem cut.
- 9. RIH w/1.56" "Super Cutter" & CCL down LT & cut LT 2 3/8" 5.95# C-75 CS Hyd below "FA" pkr as deep as possible below Morrow perfs (12,898'-13,153'). POH w/1.56" Super Cutter.
- 10. GIH w/1 11/16" Chem. cutter & CCL down LT tbg. Locate Baker 7 5/8" "FA" pkr & parallel flow tube @ 11,465'. Cut LT 2 3/8" below pkr @ +/- 11,480'(preferrably > 15' below pkr). POH w/1 11/16" cutter.
- 11. GIH w/2 1/8" Chem. Cutter down 2 7/8" LT tbg & cut @ +/- 11,390' or 2 1/2 Jts above "FA" pkr. POH w/cutter.

NOTE: OTIS 2 7/8" "S-2" profile @ 11,453' (2.313" ID) & "S-3" profile @ 11,143' (2.313" ID).

- 12. PUH w/2 7/8" LT tbg & LD 6 Jts. Re-land LT 2 7/8" tbg in tbg hanger leaving EOT @ +/- 11,210'.
- 13. PU on UT (2 3/8") tbg & prepare for back off.
- 14. RU WL w/lubricator & TIH down LT(2 7/8") w/CCL & 35' string shot. Locate LT (2 7/8") EOT. Run string shot out EOT @ +/- 11,210' & back off UT (2 3/8") tbg @ collar located between (11,210'-11,245'). RD WL.
- 15. POH & LD UT (2 3/8") 4.7# C-75 CS Hyd tbg. Call to have 2 3/8" tubing rack inspected.
- 16. POH & LD LT (2 7/8") 6.5# C-75 CS Hyd tbg.
- 17. Rig up for 24 hr operations.
- 18. GIH w/5 3/4" OS w/Cut lip guide, 4 1/4" Jars, BS, 10-4 1/4" DC's on 2 7/8" 10.4# AOH S-135 DP.
- 19. Engage UT (2 3/8") fish f/11,210'-11,245'(LT fish @ +/- 11,390') & jar short string out of parallel flow tube @ 11,465'. POH & LD fish. Note: Mx Pull = 240,000#.
- 20. TIH w/same BHA w/5 3/4" OS. Engage 2 7/8" LT fish @ +/- 11,390' & jar parallel flow tube out of "FA" pkr
 @ 11,465'. Mx Pull = 240,000#.

ARU #2 - PB DEV. & Recomplete as Single Completion Morrow Producer - 3

- 21. TIH w/6 5/8" OD flat btm KR shoe, 6"Extension, 10-4 1/4" DC's on 2 7/8" DP. Mill over 7 5/8" Baker "FA" pkr @ 11,465' (OK to chase below LT (2 3/8") TOF @ +/- 11,480'. POH w/shoe.
- 22. TIH w/5 3/4" OS w/2 3/8" grapple, Jars, BS, 10 4 1/4" DC's on 2 7/8" DP. Engage LT (2 3/8") fish & jar 2 3/8" tbg & POH & LD fish & BHA.
- 23. GIH w/6 5/8" MT bit, 10-4 1/4" DC's on 2 7/8" DP & tag LT (2 3/8") TOF below Morrow perfs f/12,898'-13,153'. CHC w/8.7 ppg BW. POH & LD BHA.
- 24. GIH w/7 5/8" CICR on 2 7/8" DP to above TOF. Load DP & pump 20 Bbls thru retainer prior to setting. Set CICR above LT tbg fish (depth determined by jet cut).
- 25. Est PIR into Devonian perfs 14,667'-14,798'.
- 26. Sqz Devonian perfs (14,667'-14,798') as determined by PIR & BLM requirements. Max Sqz pressure of 5,000 psi. POH & LD stinger & DP. WOC.
- 27. Change over from 24 hr to day light operations.
- 28. RU Tbg Testers. TIH (HT @ 6,000 psi AS following completion assy: 2 3/8" x 6' 4.7# N-80 EUE 8rd sub, 1.87" XN profile, 2 3/8" x 6' 4.7# N-80 EUE 8rd sub, 7 5/8" Hallib. PLS pkr w/OSTSD & 1.87"X profile pkr followed w/2 3/8" 4.7# C-75 CS Hyd tubing. Set pkr @ +/- 12,750' & perform push-pull test. PT csg annulus to 1,000 psi. Space out to land tubing w/8,000 lbs. tension.
- 29. Rlse on/off tool. Circ inhibited 10 ppg BW for pkr fluid. Latch back onto packer. PT csg to 1,000 psi. ND BOP & NU single completion double master valve tree.
- 30. Swab to +/- 6,000' & KO flwg.
- 31. Evaluate for acid stimulation.

