Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BURGALLOG LAND MANAGEMENT

N.M. OIL CC 3. COMMISSION
P.O. BOX 1980
HOBBS, NEW MEXICOM 882460
HOBBS, NEW MEXICOM 882460

BUREAU OF LAND MANAGEMENT	(105)	Expires: March 31, 1993
SUNDRY NOTICES AND REPORTS ON WELL	s	5. State Oil / Gas Lease No.
Do not use this form for proposals to drill or to deepen or reentry to a di	fforont recommir	LC030174B
Use "APPLICATION FOR PERMIT" for such propose	ls	6. If Indian, Alottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
Type of Well: OIL GAS OTHER Injection well		8. Well Name and Number WHRHODES B FEDERAL NCT 1
White Will,		1
Name of Operator TEXACO EXPLORATION & PRODUCTION INC		15 11064
Address and Telephone No. P.O. BOX 730, HOBBS, NM 88240	397-0426	9. API Well No. 30 025 21953
Location of Well (Footage, Sec., T., R., M., or Survey Description)		10. Field and Pool, Exploaratory Area RHODES YATES SEVEN RIVERS 5275
Init Letter A : 660 Feet From The NORTH Line and 660	_ Feet From The	RHODES YATES SEVEN RIVERS 51
AST Line Section 27 Township 26S Ran	ge <u>.37E</u>	11. County or Parish, State LEA,NEW MEXICO
Check Appropriate Box(s) To Indicate Natu	ure of Notice, Re	port, or Other Data
TYPE OF SUBMISSION		PE OF ACTION
Abandonment		Change of Plans
Recompletion		New Construction
Notice of Intent Plugging Back	•	Non-Routine Fracturing
Subsequent Report Casing Repai		Water Shut-Off
Atlering Casir	g	Conversion to Injection
Final Abandonment Notice OTHER: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give directionally drilled, give subsurface locations and measured and true verticle depths for a 1) MIRU. Pull poduction equipment, install BOP.	Conversion to Injection	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.) estimated date of starting any proposed work. If well is
Final Abandonment Notice OTHER: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give directionally drilled, give subsurface locations and measured and true verticle depths for a 1) MIRU. Pull poduction equipment, install BOP. Clean out to 3260', acidize perfs (3134-3240) w/1000 gal 15% NEFE. Rest casing/packer to 500# 30 min. (Chart to NMOCD, copy on reverse) 11-26-93: Inj 310 BWPD ② 150# RE: WFX-645	pertinent dates, including	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.) estimated date of starting any proposed work. If well is inent to this work.)*.
Final Abandonment Notice OTHER: I and give directionally drilled, give subsurface locations and measured and true verticle depths for a control of the	pertinent dates, including all markers and zones pertinent dates.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.) estimated date of starting any proposed work. If well is inent to this work.)*.
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give directionally drilled, give subsurface locations and measured and true verticle depths for a 1) MIRU. Pull poduction equipment, install BOP. 2) Clean out to 3260', acidize perfs (3134-3240) w/1000 gal 15% NEFE. 3) Ran 95 jts 2 3/8" HDPC lined inj tubing, set 4 1/2" packer @ 3097'. 4) Test casing/packer to 500# 30 min. (Chart to NMOCD, copy on reverse) 5) 11-26-93: Inj 310 BWPD @ 150# RE: WFX-645 14. Thereby certify that the foregologies true and correct SIGNATURE TITLE Engr A: TYPE OR PRINT NAME Larry W. Johnson	pertinent dates, including all markers and zones pertinent dates.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.) estimated date of starting any proposed work. If well is inent to this work.)*.

the state of

DeSoto/Nichois 12-93 ver 1.0

