

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-22128
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE X <input type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well X ☐ Gas Well ☐ Other

2. Name of Operator
Permian Resources, Inc. OGRID No. 25797

3. Address of Operator
P.O. Box 590 Midland, Texas 79701

4. Well Location

Unit Letter M : 660 feet from the South line and 660 feet from the West line

Section 8 Township 23S Range 37E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3328' GL

7. Lease Name or Unit Agreement Name:
Clift
Property No. 008976

8. Well No.
6

9. Pool name or Wildcat
Langlie Mattix 7 Rrvs Qn Grbrg 37240

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ XX

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ XX ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Permian Resources, Inc. respectfully submits the following plugging on the Clift well

8-21-02 Set cements plugs as follows:

Spot 5 sx plug on top of CIBP set @3520', calc TOC @3472'.

Spot 30 sx plug @2713', calc TOC @2424'.

Spot 30 sx plug @1207', calc TOC @918'.

WOC 4 hrs. RIH, EOT tbg @420', spot 50 sx plug.

8-22-02 RIH, tag TOC @284'; spot 10 sx surface from 93' to surface. Welder cut off 8 5/8" and 5 1/2" csg; weld on plugged well marker. RD, clean location.

Approved as to plugging of the Well Bore
Liability under bond is retained until
surface restoration is completed.
Hobbs
OC

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Barbara Watson TITLE Regulatory Compliance DATE 8-28-02

Type or print name Barbara Watson

Telephone No. 915/685-0113

(This space for State use)

APPROVED BY Harry W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE FEB 18 2003

Conditions of approval, if any, WINK

GWW

4