

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
943-0

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Port North Line Supply Company	8. Farm or Lease Name Barile State
3. Address of Operator Route 2 Box 17, Midland, Texas 79701	9. Well No. 2
4. Location of Well UNIT LETTER A 600 FEET FROM THE LINE AND 200 FEET FROM Zets West THE LINE, SECTION 36 TOWNSHIP 26S RANGE 3E NMPM.	10. Field and Pool, or Wildcat Chabasco Yates Seven Pools
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set Bridge Plug at 340' w/ 35' Cement in 200  
Circulate Hole with 25 bbls Brine w/ 23 Sacks Gel  
Set Plug 40 Sacks at 1998'  
Pump down plug with brine and 25 sacks gel per 100 bbl  
Set plug 40 Sacks at 1301  
Pump Plug down w/ brine and 25 sacks gel per 100 bbl  
Set plug 40 Sacks at 512  
Pump plug with brine and 25 sacks gel per 100 bbl  
Set plug in top of surface w/ Steel armor  
Shot pipe at 1998'  
Recovered 1908' of Pipe

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Wayne Furry</u>	TITLE <u>Sales</u>	DATE <u>3-2-73</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u>Genl.</u>	DATE <u>1-1-73</u>
CONDITIONS OF APPROVAL, IF ANY:		