SHOOT OR ACIDIZE REPAIR WELL

May 1963)		NTERIOR (Other instruction)		5. LEASE DESIGNA	Bureau No. 4 Tion and ser	
-	GEOLOGICAL SUR' SUNDRY NOTICES AND REPC this form for proposals to drill or to deepen Use "APPLICATION FOR PERMIT" f	ORTS ON WELLS	servoir.	6. IF INDIAN, ALL	-18644 OTTEE OR TRI	BE NAME
OIL GAS	S OTHER			7. UNIT AGREEMEN Dogie I		deral
2. NAME OF OPERAT	OR			8. FARM OR LEASE	NAME	
HNG Oi	1 Company	•		Dogie D	raw Fe	deral
ADDRESS OF OPER	RATOR			9. WELL NO.		
P. O.	Box 2267, Midland, Texa	as 79701 : 🌬 🐩	. Sign ()]	_	
LOCATION OF WEI See also space 17	LL (Report location clearly and in accordance to below)			10. FIELD AND POO	DL, OR WILDCA	T
At surface				Wildo	at	
1980'	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA NMPM					
				Sec. 8, 1	7-26S,	R-36E
14. PERMIT NO.	15. ELEVATIONS (Show w	whether DF, KT, GR, etc.)		12. COUNTY OR PA		
		2907.8 GR		Lea	New	Mexico
G.	Check Appropriate Box To Ind	licate Nature of Notice, I	Report, or O	ther Data		
	NOTICE OF INTENTION TO:		SUBSEQUE	ENT REPORT OF:		
TEST WATER SH	HUT-OFF PULL OR ALTER CASING	WATER SHUT-0	off	REPAIRI	NG WELL	

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OF COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

FRACTURE TREATMENT

(Other) _.

SHOOTING OR ACIDIZING

Prepare to set cement retainer at 18,300' and squeeze with 200 sks Class H cement.

Perforate Fusselman zone 18,029-51'

Acidize with 6000 gal 15% HCl and test.

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SIGNED SIGNED NUT to	መ ነ ጥር ነ	Production Clerk	DATE	12/27/74
(This space for Federal or State office use)	<u> </u>			
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE .	1914	DATE	
	Ť	OEC JOHN	X	
	*See Instruc	tions on Reverse Side		