

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-6315	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator BTA OIL PRODUCERS		8. Farm or Lease Name Lea, 7406 JV-S
3. Address of Operator 104 S. Pecos, Midland, TX 79701		9. Well No. 7
4. Location of Well UNIT LETTER <u>E</u> <u>1650</u> FEET FROM THE <u>north</u> LINE AND <u>330</u> FEET FROM THE <u>west</u> LINE, SECTION <u>28</u> TOWNSHIP <u>26-S</u> RANGE <u>36-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Comanche-Stateline (Yate)
15. Elevation (Show whether DF, RT, GR, etc.) 2903 GL		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>
	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 3270' PB 3233
Perfs 3176-3198

Proposed Procedure:

Set CIBP @ 3100' & Cap w/3sx. cmt.
Cut & Pull 5-1/2" csg. top cmt 2402'
Set 40sx cmt. plug across 5-1/2" stub
Set 50sx Cmt Plug across 8-5/8" shoe @ 1400'
Set 10sx plug @ surface
Install dry hole marker
(9.5#/gal. Mud laden fluid between plugs).

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L. H. Boyce TITLE Production Supervisor DATE 9-6-84

ORIGINAL SIGNED BY LEON BAXTON

APPROVED BY DISTRICT 1 SUPERVISOR

TITLE

DATE

SEP 12 1984

CONDITIONS OF APPROVAL, IF ANY: