

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR
DASCO Energy Corporation

3. ADDRESS OF OPERATOR
P. O. Box 755, Hobbs, NM 88241

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface 660' FNL & 1980' FEL of Sec. 10

14. PERMIT NO.
2973

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
2973

LEASE DENOMINATION AND SERIAL
NM-14502

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Federal "B"

9. WELL NO.
1

10. FIELD AND POOL OR WILDCAT
E. Sioux Tansill-Y-SR (Gas)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 10, T26S, R36E

12. COUNTY OR PARISH
Lea

13. STATE
NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETION	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON* ☒	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other)	
(Other)		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Check to state all pertinent details, and give pertinent data, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is proposed to plug as follows:

1. Set 5½" CIBP @ 3100'. Spot 5 sx Class C Cement on top of BP.
➤ Pressure test csg. & CIBP to 500 psi ^{10 PPG} SJS
2. Run 2 3/8" tbg and circulate 5½" csg with mud laden fluid.
3. Spot 10 sx Class C Cement plug from 2550' - 2454' base of salt.
4. Spot 20 sx Class C Cement plug 1550' - 1350' top of salt and 8 5/8" shoe @ 1382'.
5. Spot 5 sx plug @ surface.
6. Cut off wellhead, install dry hole marker and clean location.

18. I hereby certify that the foregoing is true and correct

SIGNED *Donna Walker*
(This space for Federal or State office use)

TITLE Agent

APPROVED BY *Donna Walker*
CONDITIONS OF APPROVAL, IF ANY

TITLE

DATE 6/15/88

DATE 6-28-88

RECEIVED

*See Instructions on Reverse Side