

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG -0191	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO CANCEL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT LIT FORM C-101 FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator BTA OIL PRODUCERS	8. Farm or Lease Name Lea "26", 7406 JV-S
3. Address of Operator 104 South Pecos Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER 'D' 760 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 26 TOWNSHIP 26-S RANGE 36-E NMPM.	10. Field and Pool, or Wildcat Comanche Stateline (Tan. Yates, 7 Rivers)
11. Elevation (Show whether DF, RT, GR, etc.) 2905' GR	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

P&A Procedure

Set CIBP @ 3100' capped w/35' cmt.

Cut & pull 5½" csg (TOC 2812')

Set 40sx cmt plug across 5½" stub - tag top of plug.

Set 50sx cmt plug @ 1456' (8-5/8" shoe) - tag top of plug.

Set 10sx cmt plug @ Surface.

Install Dry hole Marker...

NOTE: 9.5#/gal Mud Laden fluid between plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. D. Boyce R. D. BOYCE TITLE Administrative Supervisor DATE 10/20/82

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE OCT 22 1982