

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

Form C-101
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

SANTA FE, NEW MEXICO 87501

0+5-NMOCD-Hobbs 1-BW
1-File 1-Laura Richardson
1-Engr. Jim 4'WIO's
1-Foreman CK

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	For <input type="checkbox"/>
5. State Oil & Gas Lease No.	
L-5111	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Getty Oil Company	8. Farm or Lease Name Getty 28 State
3. Address of Operator P.O. Box 730, Hobbs, NM 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>J</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1680</u> FEET FROM THE <u>East</u> LINE, SECTION <u>28</u> TOWNSHIP <u>24S</u> RANGE <u>33E</u> NMPM.	10. Field and Pool, or Wildcat E. Triste Draw Delaware
15. Elevation (Show whether DF, RT, GR, etc.) 3487.1 GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Getty Oil Company proposes to plug and abandon this well as previously stated as soon as possible as follows:

1. Rig up pulling unit and install BOP.
2. Pull 2 3/8" tubing.
3. Set CIBP \pm 8280' with 30' cement on top. Install cement plug 5100-5000'.
4. Cut 7" csg at \pm 2300' (cement top @ 2335') and pull.
5. TIH with 2 3/8" tubing and set 100' cement plug 2350-2250', tag cement.
6. Raise up and spot plug 1100-1000'.
7. Set 10 sxs. surface plug and install dry hole marker.
8. Clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Area Superintendent DATE April 4, 1983

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY D.R. Crockett DISTRICT 1 SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

MAR 6 1983

RECEIVED
APR 5 1983
HOBBS OFFICE