NO. OF COPIES ACCEIVED	011	L CONSERVAT	TION DIVISI I	
DISTRIBUTION				Form C-103
SANTA FE	S	ANTA FE, NEW	MEXICO 87501	Revised 10-1
FILE U.S.G.S.				5a. Indicate Type of Lease
LAND OFFICE				State XX Foe
OPERATOR ,				5. State Oil & Gas Lease No. LG-1027
(DO HOT USK THIS FO	SUNDRY NOTICES A	OR TO DEEPEN OR PLUG AND	CK TO A DIFFERENT BESTRUGIS	
OIL GAB	OTHER-			7. Unit Agreement Name
2. Name of Operator				8. Farm or Lease Name
HNG OIL COMPANY				Pitchfork 36 State
P. O. Box 2267,	Midland, Texas 7	9702		9. Weil No.
4. Location of Well WHIT LETTER F	1980	north	1980	Wildcat Morrow
	THE, SECTION36			HMPM.
	15. EI	evation (Show whether D	7F, RT, GR. e.c.) 3377' GR	12. County Lea
. NOTIC	Check Appropriate E		iture of Notice, Report of subseq	r Other Data JENT REPORT OF: 1/31/83
PERFORM REMEDIAL WORK	7	PLUG AND ABANDON	REMEDIAL WORK	٦ :
TEMPORARILY ABANDON PULL OR ALTER CASING	<u> </u>		COMMENCE DRILLING OPHS.	ALTERING CASING PLUG AND ABANDONMENT
TEMPORARILY ABANDOM	<u> </u>		COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING OTHER		CHANGE PLANS	COMMENCE DRILLING OPHS. CASING TEST AND CEMENT JQB X OTHER	PLUG AND ABANDONMENT
OTHER		State all pertinent detail	COMMENCE DRILLING OPHS. CASING TEST AND CEMENT JQB X OTHER (Is, and give pertinent dates, inc	PLUG AND ABANDONMENT
other Proposed or Co work) see RULE 1103. 2-5-83 - Set 591	mpleted Operations (Clearly	state all pertinent details H-40 circulate	commence drilling opns. casing test and cement Job X other is, and give pertinent dates, inceed to surface.	PLUG AND ABANDONMENT
other Proposed or Co work) see Rule 1703. 2-5-83 - Set 591 Cemented	mpleted Operations (Clearly of 13-3/8" 48# I with 250 sacks H	state all pertinent details H-40 circulate HLC and 250 sack	commence drilling opns. casing test and cement Job X other is, and give pertinent dates, inceed to surface.	PLUG AND ABANDONMENT
17. Describe Proposed or Cowork) SEE RULE 1103. 2-5-83 - Set 591 Cemented 30 minut	mpleted Operations (Clearly of 13-3/8" 48# I with 250 sacks H es pressure teste	state all pertinent details H-40 circulate HLC and 250 sacked to 1500#. WC	commence drilling opns. CASING TEST AND CEMENT JQB X OTHER Is, and give pertinent dates, inc ed to surface. (S Class C.	PLUG AND ABANDONMENT
17. Describe Proposed or Cowork) SEE RULE 1103. 2-5-83 - Set 591 Cemented 30 minut	mpleted Operations (Clearly of 13-3/8" 48# I with 250 sacks H es pressure teste	state all pertinent details H-40 circulate HLC and 250 sacked to 1500#. WC	commence drilling opns. CASING TEST AND CEMENT JQB X OTHER Is, and give pertinent dates, inc ed to surface. (S Class C.	PLUG AND ABANDONMENT
17. Describe Proposed or Cowork) SEE RULE 1103. 2-5-83 - Set 591 Cemented 30 minut	mpleted Operations (Clearly of 13-3/8" 48# I with 250 sacks H es pressure teste	state all pertinent details H-40 circulate HLC and 250 sacked to 1500#. WC	other Is, and give pertinent dates, inceed to surface. CS Class C. OC - 22-3/4 hours.	PLUG AND ABANDONMENT
other 17. Describe Proposed or Comprk) SEE RULE 1703. 2-5-83 - Set 591 Cemented 30 minut	mpleted Operations (Clearly of 13-3/8" 48# I with 250 sacks H es pressure teste	state all pertinent details H-40 circulate HLC and 250 sacked to 1500#. WC	other Is, and give pertinent dates, inceed to surface. CS Class C. OC - 22-3/4 hours.	PLUG AND ABANDONMENT
other 17. Describe Proposed or Comprk) SEE RULE 1703. 2-5-83 - Set 591 Cemented 30 minut	mpleted Operations (Clearly of 13-3/8" 48# I with 250 sacks H es pressure teste	state all pertinent details H-40 circulate HLC and 250 sack d to 1500#. WC	commence objecting opens. casing rest and cement JQB X other is, and give pertinent dates, inc ed to surface. cs Class C. C - 22-3/4 hours.	PLUG AND ABANDONMENT
17. Describe Proposed or Cowork) see Rule 1703. 2-5-83 - Set 591 Cemented 30 minut	mpleted Operations (Clearly of 13-3/8" 48# I with 250 sacks H es pressure teste	state all pertinent details H-40 circulate HLC and 250 sacked to 1500#. WC	commence objecting opens. casing rest and cement JQB X other is, and give pertinent dates, inc ed to surface. cs Class C. C - 22-3/4 hours.	PLUG AND ABANDONMENT