

KLM 1/16/91

MERIDIAN OIL
MYERS B NO. 5
JALMAT FIELD (OIL)
LEA COUNTY, NEW MEXICO

GL=3383'
KB=3393'

CONDITION AFTER WORKOVER

ROD PUMP IN HOLE

PROPOSED YATES PERFS
3159'-3170' (2 SPF)
3176'-3183' (2 SPF)
3193'-3213' (2 SPF)
3234'-3242' (2 SPF)

8 5/8" 24# K-55 @414'
TOC=SURFACE

2 3/8" 4.7# J-55 TUBING

SEVEN RIVERS PERFORATIONS
3390'-3396' (1 SPF)

SEVEN RIVERS PERFORATIONS
3422'-3430' (1 SPF)
3448'-3460' (1 SPF)
BOTH SET CEMENT SQUEEZED

SEVEN RIVERS PERFORATIONS
3580'-3586' (1 SPF)
3592'-3602' (1 SPF)
3630'-3638' (1 SPF)
3660'-3668' (1 SPF)
3681'-3689' (1 SPF)

CIBP AT 3715'
WITH 15' CMT, PB=3710'

QUEEN PERFORATIONS
3718'-3722' (1 SPF)
3732'-3734' (1 SPF)
3760'-3768' (1 SPF)

PB=3790'

5 1/2" 14# K-55 @3800'
TOC=SURFACE

TD=3800'
PBD=3710'