

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division

P.O. Box 1980
Hobbs, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT - " for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Meridian Oil Inc.

3. Address and Telephone No.

P.O. Box 51810, Midland, TX 79710-1810 915-688-6943

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

NE/NW of Sec. 21, T26S, R37E
1980' FWL & 660' FNL

5. Lease Designation and Serial No.

NMLC063916

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Elliott Federal # 5

9. API Well No.

30-025-284960

10. Field and Pool, or exploratory Area

Rhodes Yts 7Rvrs

11. County or Parish, State

Lea NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other Restore to Production
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MIRU. Kill well as necessary and ND WH and NU BOP.
TOOH w/ 1947' 2 3/8" tbg. TIH w/overshot and jars. Latch onto 2 3/8" tbing fish at 1982'. Jar and recover fish. TOOH. If unsuccessful, TIH w/5 jts wash pipe an mill. Wash over tbg fish. TOOH. TIH w/overshot and jars. Latch onto tbg fish. Jar and recover fish. TOOH. TIH w/ 2 3/8" tbg and clean out well to 3325'. Land tubing at 3298'. ND BOP and NU WH. RIH w/pmp and rods. Space out pmp at surface. Return to production.

14. I hereby certify that the foregoing is true and correct

Signed

Title Regulatory Compliance

Date 9/3/96

(This space for Federal or State office use)

Approved by

Title

PETROLEUM ENGINEER

Date

SEP 25 1996

Conditions of approval, if any:

