

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Enr Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-28896
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-750
7. Lease Name or Unit Agreement Name New Mexico "EH" State
8. Well No. 1
9. Pool name or Wildcat DOUBLE X DELAWARE

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator J & G ENTERPRISE LTD. CO.
3. Address of Operator P. O. BOX 100, ARTESIA, NM 88210	4. Well Location Unit Letter P : 660 Feet From The SOUTH Line and 660 Feet From The EAST Line Section 2 Township 24S Range 32E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3609 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. 5-20 Circ. salt gel mud. Pump 25 sx "C" 4682'-4456' (DV Tool)
2. 5-20 Pump 25 sx. "C" 1154' - 928'.
3. 5-20 Pump 40 sx. "C" from 645'. WOC tag plug @ 410' (Across 8 5/8" shoe)
4. 5-20 Pump 10 sx. "C" 30' - surface.
5. 5-20 Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Larry Murray TITLE Agent DATE 6-10-97
TELEPHONE NO. _____
TYPE OR PRINT NAME _____

(This space for State Use)

APPROVED BY Charles R... TITLE ... DATE _____
CONDITIONS OF APPROVAL, IF ANY:

7-1 CW API 30 025 28896