



Arctic Exploration and Production Inc.
1625 N French Drive
Hobbs, NM 88240

1625 N French Drive
Hobbs, NM 88240

April 3, 2001

NMOCD

Attn: Chris Williams
1625 N French Drive
Hobbs, NM 88240

Will Jule -

RE: Follow-up information concerning the dual packer isolation of wellbore damage in the B.F. Harrison "B" #1 wellbore.

Dear Sir:

As agreed upon, the following information is being forwarded concerning the unorthodox repair and subsequent production of B.F. Harrison "B" #1 well (API 30-025-30200). As you may recall, this wellbore was damaged as a result of lateral drilling from the B.F. Harrison "B" #18 wellbore (API 30-025-32159). B.F. Harrison "B" #1 is completed in the Drinkard-Abo formation and the puncture occurred in the Glorietta formation. Because of the unusual situation that existed, agreement was reached whereas the damaged casing would be isolated with the use of two packers set in tandem. This would allow effective isolation between the two formations. As agreed, production rates in both wells and the annulus pressure has been monitored in the #1 well.

Attached is a history of this information, which indicates that the two packers are holding and are proving to be effective barriers between the two zones. If you have any questions concerning this information, don't hesitate to call me at (915) 688-4639.

Sincerely,

Tim N. N.

Tim N. N.

Cc File
attachments

