SUNDR	DEPARTMENT OF THE I BUREAU OF LAND MANA Y NOTICES AND REPO	GEMENT	uzo IN. Frenc	5. Lease Seria	ORM APPROVED MB No. 1004-0135 xpires November 30, 2000
Do not use th	his form for proposals to vell. Use Form 3160-3 (API	drill or to re-enter a	n		llottee or Tribe Name
SUBMIT IN TR 1. Type of Well	IPLICA IE : Other instru	clions on reverse	side 🧯		A/Agreement, Name and/or N
X Oil Well Gas Well Other				8. Well Name and No.	
2. Name of Operator Devon SFS Operating, Inc.				Turquoise "30" Federal #1 9. API Well No.	
3a. Address 20 N. Broodwoy, Swite 150		ne No. (include area code) 52_4528		30-025-33455 10. Field and Pool, or Exploratory Area	
20 N.Broadway, Suite 150 4. Location of Well (Footage, Se	(405)552-4528 on)	East Cotton Draw Field			
1,930' FNL & 1,980' FWL o	E Unit F		11. County or Lea County New Mexico	3	
12. CHECK AF	PROPRIATE BOX(ES) T	O INDICATE NATU	RE OF NOTICE, R	EPORT, OR C	OTHER DATA
TYPE OF SUBMISSION		TY	PE OF ACTION		
 Notice of Intent Subsequent Report 	 Acidize Alter Casing Casing Repair 	Deepen Fracture Treat New Construction	 Production (Star Reclamation Recomplete 	t/ Resume)	Water Shut-Off Well Integrity
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Ab	andon	
	Convert to Injection	Plug Back	Water Disposal		
Devon Proposes To Perm	anitly Plug And Abandon	As Follows:			
Devon Proposes To Perm 1. Set CIBP at 7,200' and 2. Circulate wellbore full of 3. Spot balanced cement 4. Cut off 5 1/2" casing at 5. Spot balanced cement 6. Spot balanced cement 7. Spot cement plug 0'- 5 8. Cut off 8 5/8" and 13 3. 9. Restore location.	l cap CIBP with 35' of cer of 9.5 ppg mud. plug 4,370'- 4,570' (base t 1,050'. plug 950'- 1,100' (top of plug 570'- 670' (surface 0'.	nent. e of salt at 4,300'). V salt at 1,000'). WO0 casing shoe at 622'	C. Tag plug.). WOC. Tag plug		
 Set CIBP at 7,200' and Circulate wellbore full of Spot balanced cement Cut off 5 1/2" casing at Spot balanced cement Spot balanced cement Spot balanced cement Spot cement plug 0'- 5 Cut off 8 5/8" and 13 3 	a cap CIBP with 35' of cer of 9.5 ppg mud. plug 4,370'- 4,570' (base t 1,050'. plug 950'- 1,100' (top of plug 570'- 670' (surface 0'. /8" casing 3' below groun	nent. e of salt at 4,300'). V salt at 1,000'). WOO casing shoe at 622' d level and install d	C. Tag plug.). WOC. Tag plug		
 Set CIBP at 7,200' and Circulate wellbore full of Spot balanced cement Cut off 5 1/2" casing at Spot balanced cement Spot balanced cement Spot balanced cement Spot cement plug 0'- 5 Cut off 8 5/8" and 13 3 Restore location. Note: Cement to be Class	a cap CIBP with 35' of cer of 9.5 ppg mud. plug 4,370'- 4,570' (base t 1,050'. plug 950'- 1,100' (top of plug 570'- 670' (surface 0'. /8" casing 3' below groun	nent. e of salt at 4,300'). V salt at 1,000'). WOO casing shoe at 622' d level and install d eld of 1.32 cu ft/sx.	C. Tag plug.). WOC. Tag plug		
 Set CIBP at 7,200' and Circulate wellbore full of Spot balanced cement Cut off 5 1/2" casing at Spot balanced cement Spot balanced cement Spot balanced cement Spot cement plug 0'- 5 Cut off 8 5/8" and 13 3 Restore location. Note: Cement to be Class 14. Thereby certify that the foregoin Name (Printed/Typed)	a cap CIBP with 35' of cer of 9.5 ppg mud. plug 4,370'- 4,570' (base t 1,050'. plug 950'- 1,100' (top of plug 570'- 670' (surface 0'. /8" casing 3' below groun	nent. e of salt at 4,300'). V salt at 1,000'). WOO casing shoe at 622' d level and install d eld of 1.32 cu ft/sx.	C. Tag plug.). WOC. Tag plug ry hole marker.		
 Set CIBP at 7,200' and Circulate wellbore full of Spot balanced cement Cut off 5 1/2" casing at Spot balanced cement Note: Cement plug 0'- 5 Cut off 8 5/8" and 13 3 Restore location. Note: Cement to be Class 14. Thereby certify that the foregoin Name (<i>Printed/Typed</i>) Charles H. Carleton Signature Without Balanced Without Balanced A particular	a cap CIBP with 35' of cer of 9.5 ppg mud. plug 4,370'- 4,570' (base 1,050'. plug 950'- 1,100' (top of plug 570'- 670' (surface 0'. /8" casing 3' below groun a "C" at 14.8ppg with a yie	nent. e of salt at 4,300'). V salt at 1,000'). WOO casing shoe at 622' d level and install d eld of 1.32 cu ft/sx.	C. Tag plug.). WOC. Tag plug ry hole marker. r Engineering Tecl 2002	hnician	
 Set CIBP at 7,200' and Circulate wellbore full of Spot balanced cement Cut off 5 1/2" casing at Spot balanced cement Note: cement plug 0'- 5 Cut off 8 5/8" and 13 3 Restore location. Note: Cement to be Class 14. Thereby certify that the foregoin Name (<i>Printed/Typed</i>) Charles H. Carleton Signature Wubbhaltet Applied	a cap CIBP with 35' of cer of 9.5 ppg mud. plug 4,370'- 4,570' (base 1,050'. plug 950'- 1,100' (top of plug 570'- 670' (surface 0'. /8" casing 3' below groun a "C" at 14.8ppg with a yie	nent. e of salt at 4,300'). V salt at 1,000'). WOO casing shoe at 622' d level and install d eld of 1.32 cu ft/sx. Title Senior Date 04/26/ OR FEDERAL OR S	C. Tag plug.). WOC. Tag plug ry hole marker. r Engineering Tecl 2002	hnician	
 Set CIBP at 7,200' and Circulate wellbore full of Spot balanced cement Cut off 5 1/2" casing at Spot balanced cement Note: Cement balanced cement Note: Cement to be Class 14. Thereby certify that the foregoin Name (<i>Printed/Typed</i>) Charles H. Carleton Signature <i>Multiplication Conditions of approval</i> , <i>Fany</i> , are	a cap CIBP with 35' of cer of 9.5 ppg mud. plug 4,370'- 4,570' (base t 1,050'. plug 950'- 1,100' (top of plug 570'- 670' (surface 0'. /8" casing 3' below groun a "C" at 14.8ppg with a yie cover and correct	nent. e of salt at 4,300'). V salt at 1,000'). WOO casing shoe at 622' d level and install d eld of 1.32 cu ft/sx. Title Senior Date 04/26/ COR FEDERAL OR S	C. Tag plug.). WOC. Tag plug ry hole marker. C. Engineering Tech 2002 TATE OFFICE USE Title SEE ATTA	hnician)R
 Set CIBP at 7,200' and Circulate wellbore full of Spot balanced cement Cut off 5 1/2" casing at Spot balanced cement Note: Cement to be Class I hereby certify that the foregoin Name (<i>Printed/Typed</i>) Charles H. Carleton Signature Signature Approved by ORIG. SGL Conditions of approval, frany, are certify that the applicant holds lega which would entitle the applicant holds lega which would entitle the applicant holds lega 	a cap CIBP with 35' of cer of 9.5 ppg mud. plug 4,370'- 4,570' (base i 1,050'. plug 950'- 1,100' (top of plug 570'- 670' (surface 0'. /8" casing 3' below groun a "C" at 14.8ppg with a yie ing is true and correct CV_SPHIS SPACE F DAVID F. GLASS attached. Approval of this notic al or equitable title to those rights conduct operations thereon.	nent. e of salt at 4,300'). V salt at 1,000'). WOO casing shoe at 622' d level and install d eld of 1.32 cu ft/sx. Title Senior Date 04/26/ OR FEDERAL OR S	C. Tag plug.). WOC. Tag plug ry hole marker. C. Engineering Tech 2002 TATE OFFICE USE Title SEE ATTA UNITIONS (hnician)R Roval
1. Set CIBP at 7,200' and 2. Circulate wellbore full of 3. Spot balanced cement 4. Cut off 5 1/2" casing at 5. Spot balanced cement 6. Spot balanced cement 7. Spot cement plug 0'- 5 8. Cut off 8 5/8" and 13 3 9. Restore location. Note: Cement to be Class 14. Thereby certify that the foregoin Name (Printed/Typed) Charles H. Carleton Signature Multiple State Approved by ORIG. SGL	a cap CIBP with 35' of cer of 9.5 ppg mud. plug 4,370'- 4,570' (base i 1,050'. plug 950'- 1,100' (top of plug 570'- 670' (surface 0'. /8" casing 3' below groun 6"C" at 14.8ppg with a yie ing is true and correct CVCCP HIS SPACE F DAVID F. GLASS attached. Approval of this notic al or equitable title to those rights contact operations thereon. CASE	nent. of salt at 4,300'). V salt at 1,000'). WOC casing shoe at 622' d level and install d eld of 1.32 cu ft/sx. Title Senior Date 04/26/ OR FEDERAL OR S re does not warrant or in the subject lease CON	C. Tag plug.). WOC. Tag plug ry hole marker. C. Engineering Tech 2002 TATE OFFICE USE Title SEE ATTA UNITIONS (hnician)R Roval

BECEIVED

24:8 MA S-YAM 2002 \$ AM 8:42

BUREAU OF LEND MOME



