

UNITED STATES
DEPARTMENT OF THE INTERIORSUBMIT IN TRIPI
(Other instructions
verse side)FE-
re-Form approved.
Budget Bureau No. 42-R1424.

GEOLOGICAL SURVEY

HOBBBS OFFICE O.C.C.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or to plug back into a different reservoir.
Use "APPLICATION FOR PERMIT TO DRILL" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. LC-061936 ~ A
2. NAME OF OPERATOR TEXACO Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME NONE
3. ADDRESS OF OPERATOR P. O. Box 728 - Hobbs, New Mexico		7. UNIT AGREEMENT NAME Cotton Draw Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Well located 330' from the South Line, and 330' from the East Line of Section 9, T-25-S, R-32-E, Lea County, New Mexico.		8. FARM OR LEASE NAME Cotton Draw Unit
14. PERMIT NO. Regular		9. WELL NO. 34
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3457' (D. F.)		10. FIELD AND POOL, OR WILDCAT Paduca Delaware
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 9, T-25-S, R-32-E
		12. COUNTY OR PARISH Lea
		13. STATE N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to do the following work on subject well:

1. Tag bottom with tubing, if bottom below 4726', Skip items 2 & 3.
2. Using pump truck, mud tank, tubing with saw-toothed pup-joint, & tongs to rotate, reverse circulate hole clean to 4839' with water.
3. Swab test well, if results unsuccessful, proceed to item 4.
4. Pull tubing and frac with 2500 gallons refined oil, 2500 pounds of sand, and flush with 100 bbls lease crude.
5. Swab well, recover load oil, Test, and place well on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

Dan Gillett

TITLE

Assistant District

DATE Nov. 29, 1966

(This space for Federal or State office use)

Superintendent

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side