

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

U.S. OIL CONS. COMMISSION
P.O. BOX 1980
HOT SPRING, NEW MEXICO 88240

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No.

LC-062300 LC-0619 3C

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Unit F

8. Well Name and No.

Cotton Draw Unit 33

9. API Well No.

30-02508174

10. Field and Pool, or Exploratory Area

Paduca Delaware

11. County or Parish, State

Lea, NM

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Texaco E&P, Inc.

3. Address and Telephone No.

P. O. Box 3109 - Midland, TX 79702 915/688-4816

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit F 1980' FNL, 1980' FWL Sec-10 T-25S R-32E

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Notify BLM prior to plugging and abandonment of well.
2. Rig up wireline, set CICR @ 4650'. Sqz perf. w/ 45 sx cmt.
3. Spot 25 sx cmt plug f/4650'-4450'. Circ. casing w/25# per bbl. salt gel mud.
4. POOH to 4486'. Spot 25 sx cmt plug f/4486'-4286' (B-salt 4436').
5. Perf. & sqz. @ 1192' w/pkr @ 1000' displace cmt @ 1050'. WOC & tag (top of salt 1142).
6. Perf. @ 400' & circ. cmt to surface behind 4 1/2" casing to surface. Leave casing full of cmt from 400' - surface on inside.
7. Nipple down BOP & cut off wellhead; cap well & install dry hole marker. Clean up location & move off.

14. I hereby certify that the foregoing is true and correct

Signed

[Signature]

Title Operations Engineer

Date 5/16/95

(This space for Federal or State office use)

Orig. Signed by Shannon J. Shaw

Approved by

Conditions of approval, if any:

Title

PETROLEUM ENGINEER

Date

6/22/95

24

RECEIVED

JUN 20 1966

**JOHN HOBBS
OFFICE**