16.

ARTML. OF THE INTERIOR (Other Instructions verse side)	re-	Budget Bureau No. 42-R14 5. LEASE DESIGNATION AND BERIAL N
GEOLOGICAL SURVEY, C. C.	1	LC - 061936
NOTICES AND DEPORTS ON WELLS		G. IF INDIAN, ALLOTTEE OR TRIBE NA

DEPARTI	LC-061936		
SUNDRY NOT (Do not use this form for propos Use "APPLICA"	ICES AND REPORTS ON WELLS sals to Left onto dispessor and left to a different reservoir. ATION FOR PERMIT—Ser sam products.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME NONE	
OIL GAS WELL OTHER 2. NAME OF OPERATOR	· · · · · · · · · · · · · · · · · · ·	7. UNIT AGREEMENT NAME NOWE, 8. FARM OR LEASE NAME	
	TEXACO Inc.	E.F. Ray Rederal "B"	
3. ADDRESS OF OPERATOR	P. O. Box 728 - Hobbs, New Mexico	3	
See also space 17 below.) At surface	the Newto Line and 19801 from the West	Paduca Delaware 11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA	
Line of Section 10, T-2	the North Line, and 1980' from the West 5-S, R-32-E, Lea County, N. M.	Sec. 10, T-25-S, R-32-E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 31,771 (D. F.O	12. COUNTY OR PARISH 13. STATE	
Regular	Lea N. M.		

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOT	ICE (F INTENTION TO:			SUBSEQUENT	REPORT OF:
		a		٦		F ì
TEST WATER SHUT-OFF	1	PULL OR ALTER CASING			WATER SHUT-OFF	REPAIRING WELL
	45				FRACTURE TREATMENT	ALTERING CASING
FRACTURE TREAT	1	MULTIPLE COMPLETE	l	ŀ	TRECTOR INC.	_
	1	ABANDON*	i	ľ	SHOOTING OR ACIDIZING	ABANDONMENT*
SHOOT OR ACIDIZE	I	- ADAMOON		i	<u> </u>	1 1
REPAIR WELL		CHANGE PLANS			(Other)	ultiple completion on Well
		-	1	Ì	(NOTE: Report results of m Completion or Recompletion	Report and Log form.)
(Other)			ــــــــــــــــــــــــــــــــــــــ	J _	Completion of Recompletion	Accepte and and and

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

We propose to do the following work on subject well:

- Tag bottom with tubing, if bottom below 47621, skip items 2 & 3.
- Using pump truck, mud tank, tubing with saw-toothed pup-joint, & tongs to rotate, reverse circulate hole clean to 4768' with water.
- 3. Swab test well, if results unsuccessful, proceed to item 4.
- Pull tubing, and frac with 2500 gallons refined oil, 2500 pounds of sand, and flush with 100 bbls lease crude.
- Swab well, recover load oil, Test, and place well on production.

18. I hereby certify that the foregoing is true and correct SIGNED Don Gillott	Title _	Assistant District	Nov. 29, 1966
(This space for Federal or State office use)	TITLE _	Superintendent PRO	966 DATE
	Instruct	A. H. BH	U-VN NGINEER