

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.  
LEASE DESIGNATION AND SERIAL NO.

LC-062300

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER WSW

2. NAME OF OPERATOR

TEXACO Inc.

3. ADDRESS OF OPERATOR

P. O. Box 728 - Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1980' FNL & 1980' FEL of Section 15, Township 25-S, Range 32-E,  
Unit Letter 'G', Lea County, New Mexico.

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3445' (DF)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Cotton Draw Unit

8. FARM OR LEASE NAME

Cotton Draw Unit

9. WELL NO.

17

10. FIELD AND POOL, OR WILDCAT

Paduca Delaware

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 15, T-25-S, R-32-E  
(Unit Letter 'G')

12. COUNTY OR PARISH 13. STATE

Lea

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

Add Perforations in same

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Rig up, pull tubing. Install BOP.
2. Set cement retainer @ 4660'.
3. Squeeze 4-1/2" csg perforations 4707-4735' w/350 sx Class 'C' cement w/5% Halad 22 (low fluid loss cement) & 3# Rock Salt per sx. Follow w/50 sx Class 'C' w/2% KCL. WOC 18 hrs. Test.
4. Drill out to 4766'.
5. Perforate 4-1/2" csg w/1 JSPF from 4703-4714'.
6. Set RBP @ 4720' and spot 250 gals 15% NE acid across perforations 4703-4714'.
7. Acidize perforations 4703-4714' w/1000 gals. 15% FE acid. Flush w/fresh water.
8. Run injection tubing and packer.
9. Return to injection.

APPROVED

MAY 17 1976

BERNARD MOROZ  
ACTING DISTRICT ENGINEER

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Asst. Dist. Supt.

DATE 5-11-76

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

ACCEPTED FOR RECORD

MAY 17 1976

U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

RECEIVED

11-28-1976  
U.S. INFORMATION BOARD  
P. E.