

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRI/ ATE*
(Other instruction. n re.
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME NONE	
2. NAME OF OPERATOR TEXACO Inc.		7. UNIT AGREEMENT NAME Cotton Draw Unit	
3. ADDRESS OF OPERATOR P. O. Box 728 - Hobbs, New Mexico		8. FARM OR LEASE NAME Cotton Draw Unit	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Well located 1980' from the South Line, and 1980' from the West Line of Section 15, T-25-S, R-32-E, Lea County, N. M.		9. WELL NO. 8	
14. PERMIT NO. Regular		10. FIELD AND POOL, OR WILDCAT Paduca Delaware	
15. ELEVATIONS (Show whether DF, RT, OR, etc.) 3434' (D. F.)		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 15, T-25-S, R-32-E	
		12. COUNTY OR PARISH Lea	
		13. STATE N. M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to do the following work on subject well:

1. Pull rods & tubing, and clean out to the total depth of 4720'.
2. Frac well with 2500 gallons refined oil & 2500 pounds of sand.
3. Swab well, recover load oil, Test, and place well on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

Dan Gillett

TITLE Assistant District

DATE September 23, 1966

(This space for Federal or State office use)

Superintendent

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

SEP 23 1966

A. R. BROWN

DISTRICT ENGINEER

*See Instructions on Reverse Side