

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instruction
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.
LC-0623006
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
NONE
7. UNIT AGREEMENT NAME
Cotton Draw Unit
8. FARM OR LEASE NAME
Cotton Draw Unit
9. WELL NO.
12
10. FIELD AND POOL, OR WILDCAT
Paduca Delaware
11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA
Sec. 15, T-25-S, R-32-E
12. COUNTY OR PARISH
Lea
13. STATE
N. M.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
TEXACO Inc.
3. ADDRESS OF OPERATOR
P. O. Box 728 - Hobbs, New Mexico
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
Well located 1980' from the North Line, and 660' from the
West Line of Section 15, T-25-S, R-32-E, Lea County, N. M.
14. PERMIT NO.
Regular
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3448' (D. F.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

☒
☐
☐
☐
☐

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

☐
☐
☐
☐
☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

☒
☐
☐
☐

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

☐
☐
☐
☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to do the following work on subject well:

1. Pull rods and tubing, clean out to the total depth of 4730'.
2. Frac well with 2000 gals refined oil, and 2000 pounds of sand.
Flush with lease crude.
3. Swab well, recover load oil, test, and place well on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

Dan Gillett
Dan Gillett

(This space for Federal or State office use)

TITLE Assistant District

DATE September 22, 1966

Superintendent

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

SEP 23 1966

A. H. BRUNN
DISTRICT ENGINEER

DATE

*See Instructions on Reverse Side