NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION	HOPPE OFFICE O. O.	Supersedes Old C-102 and C-103
	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
ANTA FE		
	Nov 30 3 29 PM 1	5a. Indicate Type of Lease
.s.g.s.		State X · Fee
AND OFFICE		5. State Oll & Gas Lease No.
PERATOR		
- · · · · · · · · · · · · · · · · · · ·		mmmmmm <del>k</del>
SUN	DRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR USE **APPLI	ICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
01L		
WELL X WELL	OTHER-	Cotton Draw Unit
Name of Operator		Cotton Draw Unit
	TEXACO Inc.	9. Well No.
Address of Operator	n o Der 209 Habbe Novi Movi 00	•••
	P. O. Box 728 - Hobbs, New Mexico	10
Location of Well	That the	10. Field and Pool, or Wildcat Paduca Delaware
- A	1980 FEET FROM THE LINE AND 1900 FEET FRO	
UNIT LETTER		
THE East LINE, SE	16 TOWNSHIP 25-S RANGE 32-E	
THELAS U LINE, SE		
mmmmmm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
		Lea
<u>'unnunun</u>	ck Appropriate Box To Indicate Nature of Notice, Report or O	ther Data
		NT REPORT OF:
NOTICE OF	F INTENTION TO: SUBSEQUEI	
		ALTERING CASING
ERFORM REMEDIAL WORK	PLUG AND ABANDON	PLUG AND ABANDONMENT
EMPORARILY ABANDON	COMMENCE DRILLING OPHS.	
ULL OR ALTER CASING		Г
OTHER		· · · · · · · · · · · · · · · · · · ·
work) SEE RULE 1103.	ed Operations (Clearly state all pertinent details, and give pertinent dates, includi	
We	propose to do the following work on subject well:	I
We 1.	propose to do the following work on subject well: Tag bottom with tubing, if bottom below 4721',	
•	Tag bottom with tubing, if bottom below 4721',	skip items 2 & 3. thed pup-joint, &
1. 2.	Tag bottom with tubing, if bottom below 4721', Using pump truck, mud tank, tubing with saw-too tongs to rotate, reverse circulate hole clean to	skip items 2 & 3. thed pup-joint, & o 4836' with water.
1. 2. 3.	Tag bottom with tubing, if bottom below 4721', Using pump truck, mud tank, tubing with saw-too tongs to rotate, reverse circulate hole clean to	skip items 2 & 3. thed pup-joint, & b 4836' with water. d to item 4. oil, 2000 pounds
1. 2. 3. 4.	Tag bottom with tubing, if bottom below 4721', Using pump truck, mud tank, tubing with saw-too tongs to rotate, reverse circulate hole clean to Swab test well, if results unsuccessful, procee Pull tubing and frac with 2000 gallons refined sand, and flush with 100 bbls lease crude. Run	skip items 2 & 3. thed pup-joint, & o 4836' with water. d to item 4. oil, 2000 pounds tubing & swab well
1. 2. 3. 4. 5.	Tag bottom with tubing, if bottom below 4721', s Using pump truck, mud tank, tubing with saw-too tongs to rotate, reverse circulate hole clean to Swab test well, if results unsuccessful, proceed Pull tubing and frac with 2000 gallons refined sand, and flush with 100 bbls lease crude. Run until sand back-flow ceases. Swab well, recover load oil, Test, and place we	skip items 2 & 3. thed pup-joint, & o 4836' with water. d to item 4. oil, 2000 pounds tubing & swab well ll on production.
1. 2. 3. 4. 5.	Tag bottom with tubing, if bottom below 4721', a Using pump truck, mud tank, tubing with saw-too tongs to rotate, reverse circulate hole clean to Swab test well, if results unsuccessful, proceed Pull tubing and frac with 2000 gallons refined sand, and flush with 100 bbls lease crude. Run until sand back-flow ceases. Swab well, recover load oil, Test, and place we	skip items 2 & 3. thed pup-joint, & o 4836' with water. d to item 4. oil, 2000 pounds tubing & swab well
1. 2. 3. 4. 5. 18. I hereby certify that the inform	Tag bottom with tubing, if bottom below 4721', a Using pump truck, mud tank, tubing with saw-too tongs to rotate, reverse circulate hole clean to Swab test well, if results unsuccessful, proceed Pull tubing and frac with 2000 gallons refined sand, and flush with 100 bbls lease crude. Run until sand back-flow ceases. Swab well, recover load oil, Test, and place we	skip items 2 & 3. thed pup-joint, & o 4836' with water. d to item 4. oil, 2000 pounds tubing & swab well ll on production.
1. 2. 3. 4. 5. 18. I hereby certify that the inform	Tag bottom with tubing, if bottom below 4721', a Using pump truck, mud tank, tubing with saw-too tongs to rotate, reverse circulate hole clean to Swab test well, if results unsuccessful, proceed Pull tubing and frac with 2000 gallons refined sand, and flush with 100 bbls lease crude. Run until sand back-flow ceases. Swab well, recover load oil, Test, and place we	skip items 2 & 3. thed pup-joint, & o 4836' with water. d to item 4. oil, 2000 pounds tubing & swab well ll on production.
1. 2. 3. 4. 5. 18. I hereby certify that the inform	Tag bottom with tubing, if bottom below 4721', a Using pump truck, mud tank, tubing with saw-too tongs to rotate, reverse circulate hole clean to Swab test well, if results unsuccessful, proceed Pull tubing and frac with 2000 gallons refined sand, and flush with 100 bbls lease crude. Run until sand back-flow ceases. Swab well, recover load oil, Test, and place we	skip items 2 & 3. thed pup-joint, & o 4836' with water. d to item 4. oil, 2000 pounds tubing & swab well ll on production.

ſ