I	DEPARTMEN. OF THE IN GEOLOGICAL SURVI			-061869		
			6. IF INDIAL	N, ALLOTTEE O	R TRIBE NAME	
SUND	RY NOTICES AND REPORT rm for proposals to drill or to deepen of use "APPLICATION FOR PERMIT" for	RIS ON WELLS			- 	
I I I I I I I I I I I I I I I I I I I	Use "APPLICATION FOR PERMIT" for	such proposals.)		REMENT NAME		
				n Draw Un		
WELL X GAS	OTHER		1	LEASE NAME		
NAME OF OPERATOR				n Draw Ur	hit '	
TEXACO In	IC.		9. WELL NO			
3. ADDRESS OF OPERATOR		20240	35			
P.O. Box 728, Hobbs, New Mexico 88240			ND POOL, OR X	VILACAT		
See also space 17 below.)				Paduca Delaware		
At surface		time and GGOI from the		., R., M., OR BLE		
Well is locate	ed 1980' from the South I Section 21, T-25-S, R-32	-E. Lea County, New	BURY	1, T-25-5		
Mexico. (Unit					••• •••	
14. PERMIT NO.	15. ELEVATIONS (Show wh	hether DF, RT, GR, etc.)	12. COUNT	T OR PARISH	18. STATE	
Regular	3395 '	(DF)	Lea	· · · · · · · · · · · · · · · · · · ·	New Maxi	
16.	Charle A propuete Box To Indi	icate Nature of Notice, Report,	or Other Data			
	TICE OF INTENTION TO:		BEQUENT REPORT			
50	[]			REPAINING WE		
TEST WATER SHUE-OFF		FRACTURE TREATMENT		ALTURING CAR		
FRACTURE TREAT	X MULTIPLE COMPLETE	-		ABANDONMENT		
SHOOT OR ACIDIZE	X ABANDON*					
LLFAIR WELL	CHANGE PLANS	(Other)	sults of multiple	completion es	Well	
Other)	COMPLETED OPERATIONS (Clearly state all well is directionally drilled, give subsurf	Completion or Re	latos including e	itimated date	of starting an	
1. Pull pro 2. Perforat	oduction rods, pump and te 4-1/2" O.D. casing w/	2 JSPF from 4596-4606'. acker and set at 4606'.	rell:			
 Pull pro Perforat Run 2-7, Spot 50 Acidize 	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations	tubing. 2 JSPF from 4596-4606'. acker and set at 4606'. '. Pull tubing to 4550' w/20.000 gals gelled 2	and set p Lease crude	acker.	ing	
 Pull pro Perforat Run 2-7. Spot 50 Acidize Frac 4-1 1# 20-44 	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations O sand. 1/40# Adomite an	tubing. 2 JSPF from 4596-4606', acker and set at 4606'. . Pull tubing to 4550' w/20,000 gals gelled 2 d 1/20# gelling agent p	and set p Lease crude	acker.	ing al	
 Pull pro Perforat Run 2-7. Spot 50 Acidize Frac 4-1 1# 20-44 stages 	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations O sand, 1/40# Adomite an using 60# unibeads after	tubing. 2 JSPF from 4596-4606', acker and set at 4606', '. Pull tubing to 4550' w/20,000 gals gelled 2 d 1/20# gelling agent p each stage.	and set p Lease crude	acker.	ing al	
 Pull pro Perforat Run 2-7. Spot 50 Acidize Frac 4-1 1# 20-44 stages 	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations O sand. 1/40# Adomite an	tubing. 2 JSPF from 4596-4606', acker and set at 4606', '. Pull tubing to 4550' w/20,000 gals gelled 2 d 1/20# gelling agent p each stage.	and set p Lease crude	acker.	ing	
 Pull pro Perforat Run 2-7, Spot 50 Acidize Frac 4-1 1# 20-40 stages 	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations O sand, 1/40# Adomite an using 60# unibeads after	tubing. 2 JSPF from 4596-4606', acker and set at 4606', '. Pull tubing to 4550' w/20,000 gals gelled 2 d 1/20# gelling agent p each stage.	and set p Lease crude	acker.	ing al	
 Pull pro Perforat Run 2-7, Spot 50 Acidize Frac 4-1 1# 20-40 stages 	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations O sand, 1/40# Adomite an using 60# unibeads after	tubing. 2 JSPF from 4596-4606', acker and set at 4606', '. Pull tubing to 4550' w/20,000 gals gelled 2 d 1/20# gelling agent p each stage.	and set p Lease crude	acker.	ing al	
 Pull pro Perforat Run 2-7, Spot 50 Acidize Frac 4-1 1# 20-44 stages 	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations O sand, 1/40# Adomite an using 60# unibeads after	tubing. 2 JSPF from 4596-4606', acker and set at 4606', '. Pull tubing to 4550' w/20,000 gals gelled 2 d 1/20# gelling agent p each stage.	and set p Lease crude	acker.	ing al	
 Pull pro Perforat Run 2-7. Spot 50 Acidize Frac 4-1 1# 20-44 stages 	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations O sand, 1/40# Adomite an using 60# unibeads after	tubing. 2 JSPF from 4596-4606', acker and set at 4606', '. Pull tubing to 4550' w/20,000 gals gelled 2 d 1/20# gelling agent p each stage.	and set p Lease crude	acker.	ing al	
 Pull pro Perforat Run 2-7, Spot 50 Acidize Frac 4-1 1# 20-40 stages 	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations O sand, 1/40# Adomite an using 60# unibeads after	tubing. 2 JSPF from 4596-4606', acker and set at 4606', '. Pull tubing to 4550' w/20,000 gals gelled 2 d 1/20# gelling agent p each stage.	and set p Lease crude	acker.	ing al	
 Pull pro Perforat Run 2-7, Spot 50 Acidize Frac 4-1 1# 20-40 stages 	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations O sand, 1/40# Adomite an using 60# unibeads after	tubing. 2 JSPF from 4596-4606', acker and set at 4606', '. Pull tubing to 4550' w/20,000 gals gelled 2 d 1/20# gelling agent p each stage.	and set p Lease crude	acker.	ing al	
 Pull pro Perforat Run 2-7, Spot 50 Acidize Frac 4-1 1# 20-40 stages 	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations O sand, 1/40# Adomite an using 60# unibeads after	tubing. 2 JSPF from 4596-4606', acker and set at 4606', '. Pull tubing to 4550' w/20,000 gals gelled 2 d 1/20# gelling agent p each stage.	and set p Lease crude	acker.	ing al	
 Pull pro Perforat Run 2-7, Spot 50 Acidize Frac 4-1 1# 20-44 stages 	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations O sand, 1/40# Adomite an using 60# unibeads after	tubing. 2 JSPF from 4596-4606', acker and set at 4606', '. Pull tubing to 4550' w/20,000 gals gelled 2 d 1/20# gelling agent p each stage.	and set p Lease crude	acker.	ing al	
 Pull pro Perforat Run 2-7, Spot 50 Acidize Frac 4-1 1# 20-44 stages 	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations O sand, 1/40# Adomite an using 60# unibeads after	tubing. 2 JSPF from 4596-4606', acker and set at 4606', '. Pull tubing to 4550' w/20,000 gals gelled 2 d 1/20# gelling agent p each stage.	and set p Lease crude	acker.	ing al	
 Pull pro Perforat Run 2-7, Spot 50 Acidize Frac 4-1 1# 20-44 stages Swab, to 	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations O sand, 1/40# Adomite an using 60# unibeads after est and return to produce	tubing. 2 JSPF from 4596-4606', acker and set at 4606', '. Pull tubing to 4550' w/20,000 gals gelled 2 d 1/20# gelling agent p each stage.	and set p Lease crude	acker.	ing al	
 Pull pro Perforat Run 2-7, Spot 50 Acidize Frac 4-1 1# 20-44 stages 	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations 0 sand, 1/40# Adomite an using 60# unibeads after est and return to produce	tubing. 2 JSPF from 4596-4606'. acker and set at 4606'. '. Pull tubing to 4550' w/20,000 gals gelled 2 d 1/20# gelling agent p each stage. etion. Assistant District	and set p lease crude per gallon	acker. in 3 equ		
 Pull pro Perforat Run 2-7, Spot 50 Acidize Frac 4-1 1# 20-44 stages Swab, to 	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations 0 sand, 1/40# Adomite an using 60# unibeads after est and return to produce	<pre>tubing. 2 JSPF from 4596-4606', acker and set at 4606'. '. Pull tubing to 4550' w/20,000 gals gelled 2 d 1/20# gelling agent p each stage. tion.</pre>	and set p lease crude per gallon	acker.		
 Pull pro Perforat Run 2-7. Spot 50 Acidize Frac 4 1# 20-40 stages Swab, to 18 I hereby certify that SIGNED	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations O sand, 1/40# Adomite an using 60# unibeads after est and return to produce	tubing. 2 JSPF from 4596-4606'. acker and set at 4606'. '. Pull tubing to 4550' w/20,000 gals gelled 2 d 1/20# gelling agent p each stage. etion. Assistant District	and set p lease crude per gallon	acker. in 3 equ		
 Pull pro Perforat Run 2-7. Spot 50 Acidize Frac 4 1# 20-40 stages Swab, to 18 I hereby certify that SIGNED	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations 0 sand, 1/40# Adomite an using 60# unibeads after est and return to produce the foregoing is true and confect the foregoing is true and confect	tubing. 2 JSPF from 4596-4606', acker and set at 4606', '. Pull tubing to 4550' w/20,000 gals gelled 2 d 1/20# gelling agent point reach stage. tion. Assistant District LE_Superintendent	and set p lease crude per gallon	acker. in 3 equ		
 Pull pro Perforat Run 2-7. Spot 50 Acidize Frac 4 1# 20-40 stages Swab, to Is I hereby certify that SIGNED	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations 0 sand, 1/40# Adomite an using 60# unibeads after est and return to produce the foregoing is true and correct Titral or State office true Titral or State office true Titreproval, IF ANY:	tubing. 2 JSPF from 4596-4606'. acker and set at 4606'. Pull tubing to 4550' w/20,000 gals gelled 2 d 1/20# gelling agent point of the stage. each stage. tion. Assistant District LE	vell: and set p lease crude ber gallon VED T969 DAT	acker. in 3 equ		
 Pull pro Perforat Run 2-7, Spot 50 Acidize Frac 4 1# 20-4(stages 1 Swab, to Swab, to 	oduction rods, pump and te 4-1/2" O.D. casing w/ /8" O.D. frac tubing w/p gal acid from 4596-4606 w/450 gals. 1/2" OD csg perforations 0 sand, 1/40# Adomite an using 60# unibeads after est and return to produce the foregoing is true and correct Titral or State office true Titral or State office true Titreproval, IF ANY:	tubing. 2 JSPF from 4596-4606'. acker and set at 4606'. Pull tubing to 4550' w/20,000 gals gelled 2 d 1/20# gelling agent point of the stage. each stage. tion. Assistant District LE	and set p lease crude per gallon	acker. in 3 equ		