5. 6.

With the same of t

UNITED STATES P. O. CONTRACTOR DE LEASE

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	LC-061869
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME COTTON Draw Unit 8. FARM OR LEASE NAME
1. oil	Cotton Draw Unit
2. NAME OF OPERATOR TEXACO, Inc.	57 10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR P. O. Box 728, Hobbs, New Mexico 88240	Paduca Đelaware 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 990' FSL & 990' FEL	Sec. 21, T-25-S, R-32-E 12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVATION Letter 'F') AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	Lea New Mexico 14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3386.3 (GR)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: ' TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9-330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dismeasured and true vertical depths for all markers and zones pertinent. Rig up. Pull rods and pump. Install BO	rectionally drilled, give subsurface locations and to this work.)*
Clean out. Set pkr. @ 4550'. Acidize perfs 4645'-4 Run plastic coated injection tubing W/pk Load Annulus W/inhibited water.	666' W/1000 gal 15% NEFE Acid r. and set @ 4550'.
Convert well to water injection.	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct SIGNED	Mgr _{DATE} 1-23-85
(This space for Federal or State office A CARDONS ASSESSMENT ASSES	2685
Subject to Like Approval by State TITLE TITLE See Instructions on Reverse S	

RESEIVED

FFB -6 1985

HOBES, CARCE