## SUBMIT IN TRIPLICATE (Other instructions on verse side)

Form approved. Budget Bureau No. 42-R1424.

	DEPARTM G	LC-062300				
-	SUNDRY NOTION (Do not use this form for propose Use "APPLICA"	CES AND REPORTS On the deepen of plug batton FOR PERMIT—" for such pro	N WELLS ck to a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME None		
ī.				7. UNIT AGREEMENT NAME		
	WELL X WELL OTHER	•		Cotton Draw Unit		
2.	NAME OF OPERATOR			8. FARM OR LEASE NAME		
	TEXACO I	Inc.		cotton Draw Unit		
3.	ADDRESS OF OPERATOR			O. WELL, NO.		
	P. O. Bo	ox 728, Hobbs, New Me	xi co 88240	<b>h</b>		
4.	Invalue of well (Report location clearly and in accordance with any State requirements.			10. PINED AND POOL, OR WHELEAT		
	See also space 17 below.) At surface			Paduca Delaware		
	Woll is located 660	11. MHO, T., R., M., OR BIN, AND				
	West Line of Section	Sec. 22, 25-S, R-32-E				
	Mexico. (Unit Let			, , , , , , , , , , , , , , , , , , , ,		
14.	PERMIT NO.	15. BERVATIONS (Show whether Dr.	RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE		
	Regular	31418' (D. F.)		Lea Now Mexico		
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data					
	NOTICE OF INTENTION TO:			UENT REPORT OF:		
	TEST WATER SHUT-OFF PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING WELL		
		THE OR ALLEN CASING		-		
	v	CULTURE CONCERTS	FRACTURE TREATMENT	ALTERING CASING		
	PRACTURE TERAT	CULTIPEN COMPERTS	FRACTURE TREATMENT	ABANDONMENT*		
	FRACTURE TERAT X A SHOOT OR ACIDIZE A	ABANDON®	SHOOTING OR ACIDIZING	-		
	FRACTURE THEAT  SHOOT OR ACIDIZE  REPAIR WELL		(Other)	ABANDONMENT*		
17.	FRACTURE TREAT  SHOOT OR ACIDIZE  REPAIR WELL  (Other)	MANDON®	(Other)  (Note: Report results Completion or Recomp	ABANDONM®NT*		
17.	SHOOT OR ACIDIZE  REPAIR WELL  (Other)  DESCRIBE PROPOSED OR COMPLETED OPER proposed work. If well is direction	CHANGE PLANS  RATIONS (Clearly state all pertinent nally drilled, give subsurface locations)	(Other)  (Note: Report results Completion or Recomp details, and give pertinent dates ons and measured and true vertice	anandonment*  I of multiple completion on Well letton Report and Log form.)		
17.	SHOOT OR ACIDIZE REPAIR WELL.  (Other)  DESCRIBE PROPOSED OR COMPLETED OPER proposed work. If well is direction nent to this work.)*  TEXACO PROPOSES TO DO  1. Pull Production 2. Run 2 7/8" 0. D. 3. Frac 4 1/2" 0. D  brine water conteach stage w/150/4. Pull Frac tubing	CHANGE PLANS  RATIONS (Clearly state all pertinent nally drilled, give subsurface location of the FOLLOWING WORK tubing.  Frac tubing with pace.  Casing perforations aining 1# per gallon	ON SUBJECT WELL:  cker and set @ 4600' of 20/40 sand in 3 cubing.	and an analysis of multiple completion on Well letion Report and Log form.)  Including estimated date of starting any all depths for all markers and zones perti-		

SIGNED SIGNED	TITLE .	Assistant District Superintendent	DATE	March 25, 1969
(This space for Federal or State office 1996) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE .	ADDROVE MAR 2 6 1969	DATE	