. *		***	en.		
Form (May			Form approved. Budget Bureau No. 42-R1424. LC-062300		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)				6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
i.			1977 1977	7. UNIT AGREEMENT NAME	
2. N	AME OF OPERATOR TEXACO In	c.	is crolonglatin	8. FARM OR LEASE NAME G. E. Jordan Fed. NCT-1	
3. ADDRESS OF OPERATOR P. O. BOX 728, HOBBS, NEW			The second secon	9. WELL NO. 16	aly.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) 1980 FNL & 2339 FEL of Section 28, T-25-S,				10. FIELD AND POOL, OR WILDCAT Paduca Delaware	
	R-32-E, Unit Letter 'G', Lea County, New Mexico			11. SEC., T., R., M., OR E SURVEY OR AREA	BLK. AND
				Sec. 28-T-25-	
14. P	Regular	15. ELEVATIONS (Show whether I	(DF)	Lea	New Mexico
:	FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	onamy drined, give subsurface loc	Completion or Recomp ent details, and give pertinent dates sations and measured and true vertice	ALTERING C ABANDONME s of multiple completion letion Report and Log fo, including estimated dat al depths for all marker	on Well
3.	Cut 4 1/2" casing at	freepoint and pull.	•		
4.	Spot 100' (20 sx) ce	ment across casing a	stub.		
5. Spot 100' (30 sx) cement at top of salt @ 1190'.					
6.	6. Spot 100' (30 sx) cement plug across 7 5/8" casing shoe.				
7.	Spot 20' (5 sx) ceme	nt plug at surface.			
8.	Install marker and c	lean location.			
			SET ATT OF		

18. I hereby certify that the foregoing is true and correct SIGNED . (This space for Federal or State office use) APPROVED BY _______ CONDITIONS OF APPROVAL, IF ANY: TITLE *See Instructions on Reverse Side ARTHIR R. BROWN
OISTRICT ENGINEER

1077

HOBBS, N. M.

U. S. GEOLOGICAL SURVEY P. O. Box 1157 Hobbs, New Mexico 88240

Re: Permanent Abandonment

Well: 16 G. E. Jordan Fed.NCT-1

CONDITIONS OF APPROVAL

 Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases".

- 2. The Hobbs office (telephone (505) 393-3612) is to be notified in sufficient time for a representative to witness all plugging operations.
- 3. Blowout prevention equipment is required.
- 4. In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e. ripping of pad and/or access road, reseeding, etc. We have asked the Bureau of Land Management for the surface restoration requirements for this well and we should be able to furnish you these requirements within 30 days. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.
- 5. At step 4, minimum cement plug across casing stub should be 35 sacks.
- 6. Additional 35 sack plug is to be set in interval between 750-850 feet. Plug is to be tagged to make sure plug is in place.
- 7. If $4\frac{1}{2}$ " casing is not cut and pulled from below 1200 feet contact USGS for approval of change in plugging procedure.

10107

GIL COMMANDER N COMM.