

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.  
02-J-12-25S-36E

7. Lease Name or Unit Agreement Name  
Maralo Jalmat Yates Unit

8. Well No.  
2

9. Pool name or Wildcat  
Jalmat Tansill Yates Seven Rivers

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
Maralo, Inc.

3. Address of Operator  
P. O. Box 832, Midland, Texas 79702 0832

4. Well Location 2310 4400 South  
Unit Letter J : 230 Feet From The North Line and 1650 Feet From The East Line  
Section 12 Township 25-S Range 36-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 2800'. Cap w/35' cmt (5 sx.).
2. Load hole with 10#/gal mud laden fluid using 25# gel/bbl.
3. Cut and pull 5 1/2" casing. Estimated top of cement @ 935'.
4. Set 100' (30 sx) cmt plug across 5 1/2" casing stub, 50' inside and 50' outside.
5. Set 100' (45 sx) cmt plug across base of 10 3/4" casing 50' inside and 50' outside.
6. Set 10 sx cmt plug @ surface.
7. Remove wellhead, cut off casing & weld plate on casing.
8. Clean up location.
9. Place a metal dry hole marker at location signifying operators name, well location (section, township and range) and well footage from section boundary.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Brenda Coffey TITLE Agent DATE 10-4-91

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

Orig. Signed by  
Paul Kautz  
Geologist

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE NOTIFIED 24  
HOURS PRIOR TO THE BEGINNING OF  
PLUGGING OPERATIONS FOR THE C-103  
TO BE APPROVED.

RECEIVED

OCT 07 1991

RECEIVED