

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPlicate
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

~~N.A.~~ LC 032581(4)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Sholes "B"

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Jalmat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 13, T-25-S, R-36-E

12. COUNTY OR PARISH 13. STATE

Lea

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ P.A.

2. NAME OF OPERATOR
Maralo, Inc. (Continental)

3. ADDRESS OF OPERATOR
P. O. Box 832 Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Unit Letter "F", 2310' FNL and 2310' FWL,
Section 13, T-25-S, R-36-E

14. PERMIT NO.

N.A.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

N.A.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

Re-enter & Re-plug ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Remove surface plug; re-open pit on location pad.

Remove cement plug from 2540' to 2569'.

Replug as follows:

- 1) 5 1/2" casing set @ 3242', set 40 sx plug, 50' in & out of 5 1/2" from 3292' to 3192'.
- 2) Displace hole with fresh water containing 5# gel per bbl; tag cement plug @ 3192'.
- 3) 5 1/2" casing shot off @ 2570'; set 40 sx plug, 50' in & out of 5 1/2" from 2620' to 2520'.
- 4) 8 5/8" set @ 1767', set 40 sx plug, 50' in & out of 8 5/8" from 1817' to 1717'.
- 5) T/Anhy @ 1165'; set 50 sx plug from 1150' to 1050'.
- 6) Set 10 sx plug at surface.

DEC 18 1979

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Drilling Superintendent DATE December 17, 1979

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

JAN 17 1980

TITLE

DATE

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side