

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
Maralo, Inc.

3. Address and Telephone No.

P. O. Box 832, Midland, Texas 79702 0832 915 684-7441

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FSL & 660' FEL Unit P

5. Lease Designation and Serial No.
LC 032581 (B)

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.
Sholes "B" #2

9. API Well No.
30-025-04806

10. Field and Pool, or Exploratory Area

Cooper-Jal Jalmet

11. County or Parish, State

Lea, New Mexico

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Notify NMOCC when plugging begins.
2. Set CIBP capped w/35' cmt. @ +/- 2925'.
3. Load hole with 10# mud laden fluid.
4. Set 100' (30 sx) plug across top Yates from 2673 - 2783' inside 7" csg.
5. Determine free-point cut & pull 7" csg.
6. Set 100' plug (30 sx) across 7" csg. stub.
7. Set 100' plug (30 sx) across base 8 5/8" csg. 1175' - 1275'.
8. Determine free-point cut & pull 8 5/8" csg.
9. Set 100' (40 sx) plug across 8" csg. stub.
10. Set 100' (40 sx) plug across base of 10 3/4" csg. 360' - 460'.
11. Set surface plug w/10 sx. cmt.
12. Remove wellhead, cut off casing & weld plate on csg.
13. Clean location and set dry hole marker.

14. I hereby certify that the foregoing is true and correct

Signed Brenda Coffman Title Agent

(This space for Federal or State office use)

Date March 3, 1992

Approved by David R. Glass Title _____

Conditions of approval, if any:

Date 3-11-92

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side