DISTRIBUTION SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION FILE U.S.O.S. SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION SAL ADDRESS No. SANTA FE U.S.O.S. SANTA FE S	NO. OF COPIES RECEI	VED					Form C-103	
NEW MEXICO OIL CONSERVATION COMMISSION Statistics Section Statistics Section Section	DISTRIBUTION	1	1			7		
LAND OFFICE OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS OFFICE OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS OFFICE OPERATOR SEAT OF SUNDRY NOTICES AND REPORTS ON WELLS OFFICE OF	SANTA FE		NEW	MEXICO OIL CON	SERVATION CO	MMISSION		
Check Appropriate Box To Indicate Nature of Notice, Report of Other Pata Subsequent Report of Control of C	FILE			_	77-29	7		
Support Notices And Reports On Well Support Su			_	• • •		. \$		pe of Lease
SUNDRY NOTICES AND REPORTS ON WELLS SUBSEQUENT REPORT OF MEXICO "A" Notice "A" Skally Oil Company South			_					
SUNDRY NOTICES AND REPORTS ON WELLS Supported the state of the state	OPERATOR		J					
2. Notice of Operator Skelly Oil Company Skelly Oil Company 1. Address of Operator Skelly Oil Company Skelly Oil Company 1. Address of Operator Box 730 - Hobbs, New Mexico 1. Well No. 2. The American I 1980 1. Address of Operator 1. Sept		CLINIDE	V NOTICES A				3-13	21 ************************************
2, Name of Copendors	(DO NOT USE T	SUNUK HIS FORM FOR PRO	Y NUTICES A	AND REPORTS OF	WELLS	NT RESERVOIR.		
Skelly Oil Company Skelly Oil Company Box 730 - Robbe, New Mexico 2, Location of Wall List terrer 1980 10, First room 25-S 26-B 10, First and pol, or Wildest 27-S 28-S 2	1.		TON TON PENNITT E	(FORM C-101) FOR SC	CH PROPOSALS.)		7. Unit Agreeme	ent Name
Skelly 011 Company South			OTHER-					
Box 730 - Hobbe, New Mexico 1 1980 FEST FROM THE SOUTH LINE AND 660 FEST FROM THE SOUTH LINE AND ADDRESS OF THE SOUTH LINE OF THE SOUTH LINE OF THE FEST AND CHARLES OF THE SOUTH LINE OF T	2. Name of Operator			· · · · · · · · · · · · · · · · · · ·			8. Farm or Leas	se Name
Box 730 - Hobbs, New Mexico 1. 1980 FEST FROM THE South 1017 AND 660 THE SEAR LINE, SECTION 36 TOWNSHIP 25-8 BASES 36-8 NUMBER 1017 AND 102 AND ADDRESS OF THE SOUTH 1017 AND ADD		Skelly	Oil Company	у			Mexi	co "A"
ALCONOMIC PLANS THE BASE LINE, SECTION 36 TOWNSHIP 25-8 Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: THE STAND OF PLANS CHANGE PLANS ALTERING CARING ALTERING CARING CHANGE PLANS CHANGE	3. Address of Operator							
THE BASE LINE, SECTION 36 TOWNSHIP 25-S SANGE 36-B HAPPEN 12. COUNTY REPORT OF: PLUG AND ARABOUT 12. COUNTY REPORT OF: SUBSEQUENT REPORT OF: PLUG AND ARABOUT 12. COUNTY REPORT OF: SUBSEQUENT REPORT OF: PLUG AND ARABOUT 12. COUNTY 12. COU	4 Loggtion of Wall	Box 730	- Hobbs, 1	New Mexico				2
The East the section 36 rowsers 25-8 range 36-8 range. 12. County 2983' DF 12. County 12.			006					ool, or Wildcat
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORARILY ADARDON PULL OR ALTERING CABING THE OTHER 17. Describe Proposed or Completed Operations (Clearly value all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) THE PROPOSED OF THE TOTAL THE PROPOSED OF	UNIT LETTER	1	980 FEET F	FROM THESOUT	LINE AND	660 FEET FRO	Jalm	at
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TELEPORATIVE AND ADADON FLUE ON ALTERING CARING THERE 17. Describe Proposed or Completed Operations (Clearly state all perstness dessite, and give perstness dates, including estimated date of starting any proposed work) THE NULL TIGS. Hexico "A" Well No. 2 is a temporarily abandoned well. We propose to plug and abandon this well as follows: 1. Set 60-sack cement plug over perforated interval 2807-2917'. 2. Locate freepoint indicator. Shoet and pull 7" casing. 3. Set 25-sack cement plug at top of 7" casing stub. (Rst. 2400') 4. Set 25-sack cement plug at base of surface casing at 1325'. 6. Set 10-sack cement cap at surface. Install 4" dry hole marker. HOTE: Intervals not cemented will be filled with heavy mud laden fluid. 1. Describy certify that the information above is true and complete to the best of my knowledge and belief. 1. Describy certify that the information above is true and complete to the best of my knowledge and belief.	Logi		24	9 tr (
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORABLY ABANDON TEMPORABLY ABANDON TEMPORABLY ABANDON TEMPORABLY ABANDON TO THE PLUS AND ABANDON TEMPORAL CASING TEST AND CEMENT JUS AND ABANDONMENT TO THE PLUS OF ALTER CASING THE PLUS OF ALTER CAS	THE BRANCE	LINE, SECTION	ли <u>Эб</u>	TOWNSHIP	RANGE	36-E NMP	M. (
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM ALMEDIAL WORK TEMPORABLY ABANDON PULL OR ALTER CASING THER 17. Dancettle Pippead or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or Notice ("A" Well No. 2 is a temporarily abandoned well. We propose to plug and abandon this well as follows: 1. Set 60-sack cement plug over perforated interval 2807-2917'. 2. Locate freepoint indicator. Shoot and pull 7" casing. 3. Set 25-sack cement plug at top of 7" casing stub. (Est. 2400') 4. Set 25-sack cement plug at 1730'. 5. Set 35-sack cement plug at base of surface casing at 1325'. 6. Set 10-sack cement cap at surface. Install 4" dry hole marker. HOTE: Intervals not cemented will be filled with heavy mud laden fluid. Studied in the Player of the Player of the best of my knowledge and belief. Studied in the Player of the Player of the Best of my knowledge and belief. Perform Almedial work Plug And Abandon Here Alterns casing		THITT	15. El	levation (Show whethe	r DF, RT, GR, etc	.)	12 County	4444444
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM NEMERIAL WORK TEMPORALLY ABANDON PULL OR ALTER CASING PULL OR ALTER CASING CHANGE PLANS C					, , , , , , , , , , , , , , , , , , , ,	•/	12. County	
PERFORM AEMEDIAL WORK TEMPORABLY ABANDON PULL ON ATTER CASING TOWNSEE PLANS TOWNSEE PROPOSED OF Completed Operations (Clearly state all pertinent dates), and give pertinent dates, including estimated date of starting any proposed work) Past 60-sack cement plug over perforated interval 2807-2917', Locate freepoint indicator. Shoot and pull 7" casing. 3. Set 25-sack cement plug at top of 7" casing stub. (Est. 2400') 4. Set 25-sack cement plug at 1730'. 5. Set 35-sack cement plug at base of surface casing at 1325'. 6. Set 10-sack cement cap at surface. Install 4" dry hole marker. ***********************************	16.	Check	Appropriate P		Noture of Not	D	Lea	
PRIOR AND ABANDON REMEDIAL WORK COMMERCE BRILLING ORDS. CADING TEST AND CEMENT 100 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEC RULE 103. Mexico "A" Well No. 2 is a temporarily abandoned well. We propose to plug and abandon this well as follows: 1. Set 60-sack cement plug over perforated interval 2807-2917'. 2. Locate freepoint indicator. Shoot and pull 7" casing. 3. Set 25-sack cement plug at top of 7" casing stub. (Est. 2400') 4. Set 25-sack cement plug at 1730'. 5. Set 35-sack cement plug at base of surface casing at 1325'. 6. Set 10-sack cement cap at surface. Install 4" dry hole marker. NOTE: Intervals not cemented will be filled with heavy mud laden fluid. 8. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 1016 1016 1016 1017 1016 1017 1016 1017	. N	OTICE OF IN	TENTION TO):	Nature of Not			
TEMPORABILY ABANDON PULL OR ALTER CASING DIVER OTHER OT						3003EQUE	NI REPORT OF	:
PROUED BY LORS ALTER CASING CHANGE PLANS CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JOB OTHER OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Mexico "A" Well No. 2 is a temporarily abandoned well. We propose to plug and abandon this well as follows: 1. Set 60-sack cement plug over perforated interval 2807-2917'. 2. Locate freepoint indicator. Shoot and pull 7" casing. 3. Set 25-sack cement plug at top of 7" casing stub. (Est. 2400') 4. Set 25-sack cement plug at 1730'. 5. Set 35-sack cement plug at base of surface casing at 1325'. 6. Set 10-sack cement cap at surface. Install 4" dry hole marker. SOTE: Intervals not cemented will be filled with heavy mud laden fluid. 8. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Signal A. Fietoner The District Superintendant DATE August 15, 1967	PERFORM REMEDIAL WOR	RK	F	PLUG AND ABANDON	REMEDIAL WORK		ALTE	RING CASING
PROVER BY PROVER BY CHANGE PLANS OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see RULE 1103. Hexico "A" Well No. 2 is a temporarily abandoned well. We propose to plug and abandon this well as follows: 1. Set 60-sack cement plug over perforated interval 2807-2917'. 2. Locate freepoint indicator. Shoot and pull 7" casing. 3. Set 25-sack cement plug at top of 7" casing stub. (Est. 2400') 4. Set 25-sack cement plug at 1730'. 5. Set 35-sack cement plug at base of surface casing at 1325'. 6. Set 10-sack cement cap at surface. Install 4" dry hole marker. NOTE: Intervals not cemented will be filled with heavy mud laden fluid. Signal August 15, 1967	TEMPORARILY ABANDON				COMMENCE DRIL	LING OPNS.		<u> </u>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed areas. See Rule 1103. Maxico "A" Well No. 2 is a temporarily abandoned well. We propose to plug and abandon this well as follows: 1. Set 60-sack cement plug over perforated interval 2807-2917'. 2. Locate freepoint indicator. Shoet and pull 7" casing. 3. Set 25-sack cement plug at top of 7" casing stub. (Rst. 2400') 4. Set 25-sack cement plug at 1730'. 5. Set 35-sack cement plug at base of surface casing at 1325'. 6. Set 10-sack cement cap at surface. Install 4" dry hole marker. **ROTE:* Intervals not cemented will be filled with heavy mud laden fluid. 8. I hereby certify that the information above is true and complete to the best of my knowledge and belief. **PROVED BY** **PROVED BY** **PROVED BY** **PROVED BY** *** **PROVED BY** *** *** *** *** *** *** ***	PULL OR ALTER CASING		С	CHANGE PLANS	CASING TEST AN	D CEMENT JOB		
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed acres, see Rule 1103. Maxico "A" Well No. 2 is a temporarily abandoned well. We propose to plug and abandon this well as follows: 1. Set 60-sack cement plug over perforated interval 2807-2917'. 2. Locate freepoint indicator. Shoet and pull 7" casing. 3. Set 25-sack cement plug at top of 7" casing stub. (Est. 2400') 4. Set 25-sack cement plug at 1730'. 5. Set 35-sack cement plug at base of surface casing at 1325'. 6. Set 10-sack cement cap at surface. Install 4" dry hole marker. ***********************************					OTHER			
Maxico "A" Well No. 2 is a temporarily abandoned well. We propose to plug and abandon this well as follows: 1. Set 60-sack cement plug over perforated interval 2807-2917'. 2. Locate freepoint indicator. Shoet and pull 7" casing. 3. Set 25-sack cement plug at top of 7" casing stub. (Est. 2400') 4. Set 25-sack cement plug at 1730'. 5. Set 35-sack cement plug at base of surface casing at 1325'. 6. Set 10-sack cement cap at surface. Install 4" dry hole marker. MOTE: Intervals not cemented will be filled with heavy mud laden fluid. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 19. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	ЛЭНТС							
Maxico "A" Well No. 2 is a temporarily abandoned well. We propose to plug and abandon this well as follows: 1. Set 60-sack cement plug over perforated interval 2807-2917'. 2. Locate freepoint indicator. Shoet and pull 7" casing. 3. Set 25-sack cement plug at top of 7" casing stub. (Est. 2400') 4. Set 25-sack cement plug at 1730'. 5. Set 35-sack cement plug at base of surface casing at 1325'. 6. Set 10-sack cement cap at surface. Install 4" dry hole marker. MOTE: Intervals not cemented will be filled with heavy mud laden fluid. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 19. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	17. Describe Proposed	or Completed Op	erations (Clearly	state all pertinent de	tails and give per	tinant datas in al. Ji		
1. Set 60-sack cement plug over perforated interval 2807-2917'. 2. Locate freepoint indicator. Shoot and pull 7" casing. 3. Set 25-sack cement plug at top of 7" casing stub. (Est. 2400') 4. Set 25-sack cement plug at 1730'. 5. Set 35-sack cement plug at base of surface casing at 1325'. 6. Set 10-sack cement cap at surface. Install 4" dry hole marker. BOTE: Intervals not cemented will be filled with heavy mud laden fluid. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Signature. Signature. District Superintendent. DATE August 15, 1967	WORK) SEE RULE 1	. 103.				,	,	starting any propose
1. Set 60-sack cement plug over perforated interval 2807-2917'. 2. Locate freepoint indicator. Shoot and pull 7" casing. 3. Set 25-sack cement plug at top of 7" casing stub. (Est. 2400') 4. Set 25-sack cement plug at 1730'. 5. Set 35-sack cement plug at base of surface casing at 1325'. 6. Set 10-sack cement cap at surface. Install 4" dry hole marker. BOTE: Intervals not cemented will be filled with heavy mud laden fluid. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Signature. Signature. District Superintendent. DATE August 15, 1967	Mexico '	'A" Well No	o. 2 is a t	temporarily at	andoned we	11. He sweet	es to olive.	ä
2. Locate freepoint indicator. Shoot and pull 7" casing. 3. Set 25-sack cement plug at top of 7" casing stub. (Est. 2400') 4. Set 25-sack cement plug at 1730'. 5. Set 35-sack cement plug at base of surface casing at 1325'. 6. Set 10-sack cement cap at surface. Install 4" dry hole marker. HOTE: Intervals not cemented will be filled with heavy mud laden fluid. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Signal 1. Fletcher Title District Superintendent DATE August 15, 1967	a ban d on	this well	as follows):		rre me broke	me to brok :	ano.
2. Locate freepoint indicator. Shoot and pull 7" casing. 3. Set 25-sack cement plug at top of 7" casing stub. (Est. 2400') 4. Set 25-sack cement plug at 1730'. 5. Set 35-sack cement plug at base of surface casing at 1325'. 6. Set 10-sack cement cap at surface. Install 4" dry hole marker. ***********************************								
2. Locate freepoint indicator. Shoot and pull 7" casing. 3. Set 25-sack cement plug at top of 7" casing stub. (Est. 2400') 4. Set 25-sack cement plug at 1730'. 5. Set 35-sack cement plug at base of surface casing at 1325'. 6. Set 10-sack cement cap at surface. Install 4" dry hole marker. **BOTE:** Intervals not cemented will be filled with heavy mud laden fluid. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		1. Set	60-sack ce	ment plug ove	er perforate	ed interval 2	807-2917'.	
3. Set 25-sack cement plug at top of 7" casing stub. (Est. 2400') 4. Set 25-sack cement plug at 1730'. 5. Set 35-sack cement plug at base of surface casing at 1325'. 6. Set 10-sack cement cap at surface. Install 4" dry hole marker. ROTE: Intervals not cemented will be filled with heavy mud laden fluid. 8. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Signal 7. b. Fletcher Title District Superintendent DATE August 15, 1967								
4. Set 25-sack cement plug at 1730'. 5. Set 35-sack cement plug at base of surface casing at 1325'. 6. Set 10-sack cement cap at surface. Install 4" dry hole marker. NOTE: Intervals not cemented will be filled with heavy mud laden fluid. 8. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED THE District Superintendent DATE August 15, 1967		Z. Loc:	ste freepoi	int indicator.	Shoot and	d pull 7" cas	ing.	
4. Set 25-sack cement plug at 1730'. 5. Set 35-sack cement plug at base of surface casing at 1325'. 6. Set 10-sack cement cap at surface. Install 4" dry hole marker. NOTE: Intervals not cemented will be filled with heavy mud laden fluid. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		3 800	25-anak an					
5. Set 35-sack coment plug at base of surface casing at 1325'. 6. Set 10-sack coment cap at surface. Install 4" dry hole marker. NOTE: Intervals not comented will be filled with heavy mud laden fluid. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		J. #66	47-mater ce	ment bing at	top of 7"	casing stub.	(Est. 2400'))
5. Set 35-sack coment plug at base of surface casing at 1325'. 6. Set 10-sack coment cap at surface. Install 4" dry hole marker. ROTE: Intervals not comented will be filled with heavy mud laden fluid. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Signature 15. Peroved by		4. Set	25-sack ca	mont also of	1720			
6. Set 10-sack cement cap at surface. Install 4" dry hole marker. NOTE: Intervals not cemented will be filled with heavy mud laden fluid. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Signal 1. Fletcher Title District Superintendent DATE August 15, 1967				mone brog ar	1730 .			
6. Set 10-sack cement cap at surface. Install 4" dry hole marker. NOTE: Intervals not cemented will be filled with heavy mud laden fluid. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED TITLE District Superintendent DATE August 15, 1967		5. Set	35-sack ce	ment plug at	base of sur	rface contro	at 1395!	
BOTE: Intervals not cemented will be filled with heavy mud laden fluid. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 19. I letoner TITLE District Superintendent DATE August 15, 1967						~		
BOTE: Intervals not cemented will be filled with heavy mud laden fluid. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 19. I letoner TITLE District Superintendent DATE August 15, 1967		6. Set	10-sack ce	ment cap at s	urface. In	stall 4" dry	hole marker	•
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Signed Signed Title District Superintendent DATE August 15, 1967								
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Signed Signed Title District Superintendent DATE August 15, 1967		HOTE:]	intervals n	ot cemented w	ill be fill	ed with heav	y mud laden	fluid.
SIGNED SIGNED THE District Superintendent DATE August 15, 1967							•	•
IGNED SIGNED TO BE SIGNED TITLE District Superintendent DATE August 15, 1967								
IGNED SIGNED TO BE BY SIGNED TITLE District Superintendent DATE August 15, 1967	8. I hereby certify that	the information	above is true and	complete to the best	of my knowledge a	nd belief.		
PPROVED BY		· · · · · · · · · · · · · · · · · · ·						
PPROVED BY	IGNED	المستفر المستفرق المرادات	: b. Fletch	ler minis bi	strict Suma	rintendent		16 16/5
		} 				**************************************	DATE AUSU	ac 13, 1967
								-
DATE	PPROVED BY			TITLE			B	

CONDITIONS OF APPROVAL, IF ANY