01 1 1004)	TED STATES 'T OF THE INTE	ROR		FORM APPROVE Budget Bureau No. 100	4-0135
	LAND MANAGE		Oil Lons. Di	Expires July 31, 199	6
SUNDRY NOTICES		ON WELLS 162	5 N. French D	IC-032450 (A	
Do not use this form for abandoned well. Use For	proposals to drill of	r to re-enter an Hob	bs, NM 8824	Indian, Allottee or Tribe N	lame
SUBMIT IN TRIPLICATE	7	7. If Unit or CA/Agreement, Name and/or No. <b>NM-71037X</b>			
I. Type of Well Oil X Gas Well Other	8	. Well Name and No.			
2. Name of Operator		South Mattix No. 11 Unit Federal			
Altura Energy L/ID	9	9. API Well No.			
3a. Address <b>P.O. Box 4294, Houston, TX 77210</b> -	3b. Phone No. (include area (281) 552-1158				
Lecation of Well (Footage, Sec., T., R., M., or Survey Descript			10. Field and Pool, or Exploratory Area Fowler; Upper Paddock (Gas)		
Letter H, 2310' FNL x 330' FEL, S	1	11. County or Parish, State			
12. CHECK APPROPRI				Lea Co.	<u>NM</u>
		DICATE NATURE OF		ROTHER DATA	
TYPE OF SUBMISSION	· · · · · · · · · · · · · · · · · · ·	Т	YPE OF ACTION		
X Notice of Intent	Acidize	Deepen	Production (Sta	art/Resume) Water Si	nut-Off
	Alter Casing	Fracture Treat	Reclamation	Well Inte	grity
Subsequent Report	Casing Repair	New Construction	X Recomplete	Other	
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Al	bandon	
	Convert to Injectio	on 🗌 Plug Back	Water Disposal		
The subject well is currently a	shut-in gas wel	l in the Fowler; 1	Upper Paddock ((	Gas) Pool. The pro	posed
operation is to recomplete the v attached procedure.	xell as an oil wa	ell in the Fowler	; Drinkard Pool	(26220) as per tl	).e
<ol> <li>I hereby certify that the foregoing is true and correct Name (Printed/Typed)</li> </ol>	· · · · · · · · · · · · · · · · · · ·	Title			
Mark Stephens Mar	K. Stephens	в	usiness Analyst	(SG)	
	,	Date 03	/07/2000		
	SPACE FOR FED	ERAL OR STATE OF	FICE USE		<u></u>
A 11			IM ENGINEE	MAR 17	2000
Approved by Conditions of approval, if any, are attached. Approval of certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations thereon.	this notice does not w those rights in the subj	atrant or ost			
Title 18 U.S.C. Section 1001, makes it a crime for any fraudulent statements or representations as to any matter with	person knowingly and y hin its jurisdiction.	willfully to make to any d	epartment or agency of	the United States any fals	e, fictitious o
Insugions offeverse mark and the	rufmile a	(102 al.	Ala M.	· 1. 1.D /	11
Insugings offeverse Mark need to	mont a	· Cive per	for du	and top	-Chu
			-		1. 1. 1. 1. 1.

Gians affeverse Mork	need	to submit a	C102 plat for	Quinkard Prot - Chins
				1. 1. There

# CEALEOT

### IS :11 ∀ EI 881 1007

HOOMERF OLLIOS

. H



NEXTON LAND THE NEXT OF A

2003 MAR 13 🔥 NH 50

en le Martino parte en ve

#### SMU #11 RECOMPLETION TO DRINKARD FORMATION

#### **RECOMMENDED PROCEDURE**

- 1. MIRU pulling unit. Kill well with field saltwater. ND wellhead and NU BOP'S.
- 2. POH with 2 3/8-inch plastic coated tubing string and seal assembly, LD tubing while POH.
- 3. PU 2 7/8 inch tubing string, mill and packer plucker assembly. RIH and mill up slips on Guiberson permanent packer and POH with permanent packer.
- 4. RIH with 2 7/8 inch tubing and squeeze packer and squeeze open Upper Paddock perforations from 4810-4835 feet with 50-75 sacks of LWL neat cement with additives for adequate pump time. WOC.
- 5. POH with tbg and squeeze packer. PU collars and bit and RIH to top of cement. DO cement to approximately 4865 feet (cement top on bridge plug). Circulate hole clean and pressure test squeezed perfs to 500-750 psig. If squeeze holds proceed to next step. If unsuccessful pressure test, repeat steps 4 and 5.
- 6. Drill out cement and CIBP at 4875 feet and continue in hole to a depth of approximately 7200 feet. Circulate hole clean and pressure test csg to 500-750 psig.
- 7. POH with tbg. and bit. PU casing scraper and RIH to approximately 6500 feet. POH with csg. Scraper.
- 8. RU wireline unit and run GRN CBL log from 6500 feet to 4500 feet. RIH with 4 inch csg gun and perforate Drinkard formation from 6240-6250 feet with 4 spf and 60 degree phasing. (Perforation depth based on 1954 Electric log)
- 9. PU 3 <sup>1</sup>/<sub>2</sub> inch frac string and frac packer. RIH and set packer at approximately 6000 feet.
- 10. RU frac equipment and frac Drinkard Formation as per frac program to be issued later. Flow back well immediately following frac.
- 11. POH with 3 <sup>1</sup>/<sub>2</sub> inch frac string LD tbg while POH. RIH with 2 7/8 inch open ended tbg, seating nipple and sawtooth collar on bottom. Circulate out any sand fill to a depth of 50 feet below perforations.
- 12. Set end of tubing at top of perforations. ND BOP'S and NU wellhead. Swab well to establish production and report results of test to Houston Office. RDMO.

## 

IS:!! ∀ EI 878 002

501110 CF LAVA AL

.

### 200 MAR 13 A 11: 50

an an marana a ga ga mara. Tana an sa sa sa sa sa sa