ONTHE DETION NEW MEXICO DIL CONSERVATION COMMISSION NEW MEXICO DIL CONSERVATION COMMISSION NEW MEXICO DIL CONSERVATION COMMISSION Son Longue Pres of Lamon Free (1) Son Longue Pres of Lamon Free (2) Son Longue Pres of Lamon Free (3) Son Longue Pres of Lamon Free (4) Son Longue Pres of Lamon Free (4) Son Longue Pres of Lamon Free (4) Son Longue Pres of Lamon Free (5) Son Longue Pres of Lamon Free (6) Son Longue Pres of Lamon Free (7) Son Longue Pres of Lamon Free (8) Free (NO. OF COPIES RECEIVED						Form C-103	
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES OF THE WASHINGTON OF THE WASHINGTON ON THE WEST OF	DISTRIBUTION						-	
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS DO NOT LET THE FOUNDAMENT CONTINUES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS TO THE WORLD CONTINUES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS TO THE WORLD CONTINUES AND REPORTS ON WELLS THE WORLD CONTINUES AND REPORTS ON WELLS AND REPORTS ON WELL		+ + + -	NEW MEXIC	CO OIL CONSE	RVATION CO	MMISSION		
SUBJECTION SUNDEY NOTICES AND REPORTS ON WELLS TO THE TALL SOURCE SURVEY OF THE SURVEY								
SUNDRY NOTICES AND REPORTS ON WELLS Re Not all frag forty and recording to the state of the sta					Endo :		5a. Indicate Type of Le	
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS TO A STATE PRODUCT OF THE PRODUCT OF		+	•				State	Fee 👗
SUNDRY NOTICES AND REPORTS ON WELLS ON NOTICES THE PROPERTY OF THE PROPERTY O		+ +					5. State Oil & Gas Leas	se No.
Langlie Mattix Noolworth Unit T. 5 Bridge of Consider Americal Petroleum Corporation Address of Operator P. 0. Box 668 - Hobbs, New Mexico Location of Wall All Langlie Mattix D. 660 recr from the North Line And 660 recr from Line Recr from 37-8 recr from Line Pool, or Million Line Line Line Line Line Line Line Lin			1					
Langlie Mattix Noolworth Unit T. 5 Bridge of Consider Americal Petroleum Corporation Address of Operator P. 0. Box 668 - Hobbs, New Mexico Location of Wall All Langlie Mattix D. 660 recr from the North Line And 660 recr from Line Recr from 37-8 recr from Line Pool, or Million Line Line Line Line Line Line Line Lin		SUNDE	Y NOTICES AND RI	FPORTS ON 1	WELLS			
Langlie Mattix Noolworth Unit T. 5 Bridge of Consider Americal Petroleum Corporation Address of Operator P. 0. Box 668 - Hobbs, New Mexico Location of Wall All Langlie Mattix D. 660 recr from the North Line And 660 recr from Line Recr from 37-8 recr from Line Pool, or Million Line Line Line Line Line Line Line Lin	(DO NOT USE THIS F US	ORM FOR PRO	POSALS TO DRILL OR TO DE	EEPEN OR PLUG BA	CK TO A DIFFERE PROPOSALS.)	NT RESERVOIR.	<u> </u>	7//////
2. Notes of Control of				-	-		7. Unit Agreement Name	•
Assertion of Committee of Committee of Special Committee of Special Committee of Co	OIL KELL WE		OTHER-		L	anglie Mattix		
P. O. Box 668 - Hobbs, New Mexico C. Ligentian of Well BATT LETTER D							8. Farm or Lease Name	
P. O. Box 668 - Hobbs, New Mexico C. Ligentian of Well BATT LETTER D	Amerada Petro	leum Co	rporation					
C. Feed Proof of Nell C. Feed Proof Tree Proof The North List and 660 FEET FROM THE NO							9. Well No.	
C. Feed Proof of Nell C. Feed Proof Tree Proof The North List and 660 FEET FROM THE NO	P. O. Box 668	- Hobb	s. New Mexico				1	
THE WEST LIME, SECTION 27 TOWNSHIP 24-S MAKE 37-SE HAMPA.							10. Field and Pool, or	Wildcat
15. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM NEWEDIAL WORK TEMPORABLE ABANDON PULL OF ALITE CASING OTHER 17. Descente Proposed of Completed Operations (Clearly state all persinent details, and give persinent dates, including estimated date of starting any proposed work) see NULE 1702. Pull production equipment. Clean out from 3508' to 3574'. Deepen from 3574' to 3610'. Run GR-N log. Acidize new hole with 500 gals. 15% acid. Resume production.	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		660 FEET FROM TH	- North	LINE AND	660 FEET FRO	Langlie Matt	t i x
15. Elevations (Show whether DF, RT, GR, etc.) 3212' GL Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORABILITY ABANDON PULL OR ALTER CASING OTHER 17. Describe Perpowed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703. Pull production equipment. Clean out from 3508' to 3574'. Deepen from 3574' to 3610'. Run GR-N log. Acidize new hole with 500 gals. 15% acid. Resume production. Lia, I hereby cerify that the information above is true and complete to the best of my knowledge and belief. PITTE Asst. Dist. Supt. CATE 8-27-68	UNIT LETTER	·-	FEET FROM TH					
15. Elevations (Show whether DF, RT, GR, etc.) 3212' GL Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORABILITY ABANDON PULL OR ALTER CASING OTHER 17. Describe Perpowed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703. Pull production equipment. Clean out from 3508' to 3574'. Deepen from 3574' to 3610'. Run GR-N log. Acidize new hole with 500 gals. 15% acid. Resume production. Lia, I hereby cerify that the information above is true and complete to the best of my knowledge and belief. PITTE Asst. Dist. Supt. CATE 8-27-68	Uast		ou 27	,suin 24_C	BANCE	37.R NAME		11111111
15. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REWEDIAL WORK PLUS AND ABANDON PULL ON ATTR CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pull production equipment. Clean out from 3508' to 3574'. Deepen from 3574' to 3610'. Run GR-N log. Acidize new hole with 500 gals. 15% acid. Resume production.	THE WEST	LINE, SECTI	UNTOWN	еэліг <u></u>	NANGE	n MPN		
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PERFORM REMEDIAL WORK PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed mork) SEE NUL E 1103. Pull production equipment. Clean out from 3508' to 3574'. Deepen from 3574' to 3610'. Run GR-N log. Acidize new hole with 500 gals. 15% acid. Resume production. 16. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 17. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	mmmm	TITT	15. Elevation	(Show whether l	OF, RT, GR, etc	.)	12. County	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PERFORM REMEDIAL WORK PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed mork) SEE NUL E 1103. Pull production equipment. Clean out from 3508' to 3574'. Deepen from 3574' to 3610'. Run GR-N log. Acidize new hole with 500 gals. 15% acid. Resume production. 16. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 17. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.							Lea	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORABILITY ABANDON THEM OTHER 17. Describe Proposed of Completed Operations (Clearly state all pertanent details, and give pertanent dates, including estimated date of starting any proposed work) Pull production equipment. Clean out from 3508' to 3574'. Deepen from 3574' to 3610'. Run GR-N log. Acidize new hole with 500 gals. 15% acid. Resume production.	16.	<i>''''''</i>				Danast or O		
PERFORM REMEDIAL WORK PULL OF ALTER CASING CHANGE PLANS CHANGE PLANS COMMENCE OFFICENCY JOB			• • •	o Indicate N	ature of Noti			
TEMPORABILY ARANGO PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pull production equipment. Clean out from 3508' to 3574'. Deepen from 3574' to 3610'. Run GR-N log. Acidize new hole with 500 gals. 15% acid. Resume production.	NOT	ICE OF I	NTENTION TO:			SUBSEQUEN	II REPORT OF:	
TEMPORABILY ARANGO PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pull production equipment. Clean out from 3508' to 3574'. Deepen from 3574' to 3610'. Run GR-N log. Acidize new hole with 500 gals. 15% acid. Resume production.	r	==1						
CHANGE PLANS OTHER OT	PERFORM REMEDIAL WORK	X	PLUG AN	D ABANDON	REMEDIAL WORK			=
17. Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pull production equipment. Clean out from 3508' to 3574'. Deepen from 3574' to 3610'. Run GR-N log. Acidize new hole with 500 gals. 15% acid. Resume production. 18. Lhereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED THEE ASSET, Dist. Supt. DATE 8-27-68	TEMPORARILY ABANDON					===	PLUG AND ABA	ANDONMENT
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pull production equipment. Clean out from 3508' to 3574'. Deepen from 3574' to 3610'. Run GR-N log. Acidize new hole with 500 gals. 15% acid. Resume production. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	PULL OR ALTER CASING		CHANGE	PLANS	CASING TEST AN	D CEMENT JOB		<u></u>
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.					OTHER			
Pull production equipment. Clean out from 3508' to 3574'. Deepen from 3574' to 3610'. Run GR-N log. Acidize new hole with 500 gals. 15% acid. Resume production. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED TITLE ABST. Dist. Supt. DATE 8-27-68	OTHER							
Pull production equipment. Clean out from 3508' to 3574'. Deepen from 3574' to 3610'. Run GR-N log. Acidize new hole with 500 gals. 15% acid. Resume production. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED TITLE ABST. Dist. Supt. DATE 8-27-68					.,			
APPROVED BY Runyan TITLE DATE DATE OATE	Pull product:	lon equi	ipment. Clean o	out from 3: hole with	508' to 35 500 gals.	74'. Deepen 15% acid. E	from 3574' to Resume production	a.
APPROVED BY	18. I hereby certify that the	e informatio			st. Dist.		DATE 8-27-	68
	APPROVED BY	4 W.	Rungan	TITLE			DATE	
		/ 41 15 42	v:					