

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- T.A.		7. Unit Agreement Name Langlie Mattix Woolworth Unit Tract 1
2. Name of Operator Amerada Petroleum Corporation		8. Farm or Lease Name
3. Address of Operator P.O. Box 668 - Hobbs, New Mexico		9. Well No. 2
4. Location of Well UNIT LETTER D , 330 FEET FROM THE North LINE AND 990 FEET FROM THE West LINE, SECTION 28 TOWNSHIP 24S RANGE 37E NMPM.		10. Field and Pool, or Wildcat Langlie Mattix
15. Elevation (Show whether DF, RT, GR, etc.) 3261' DF		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to run 6-1/8" bit on string tubing and drill collars to top of 5-1/2" liner. Run ret. bridge plug and Baker full bore cementer and squeeze hole in 7" casing 1975' to 2005' with 100 sacks cement. Drill out cement, test casing and recover bridge plug. Run 4-3/4" junk mill. Mill up bailer and clean out to 3597'. Run Gamma Ray Neutron and Caliper log from surface to TD. Run tubing, pump and rods and restore well to producing status.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>B. D. J. [Signature]</u>	TITLE <u>District Superintendent</u>	DATE <u>10-7-66</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>Engineer District 1</u>	DATE <u>10-7-66</u>
CONDITIONS OF APPROVAL, IF ANY:		