

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Box Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 3002511289
5. Indicate Type of Lease <u>Federal</u> STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No. LC032592B
7. Lease Name or Unit Agreement Name COOPER JAL UNIT
8. Well No. 232
9. Pool Name or Wildcat JALMAT TANSILL YATES SEVEN RIVERS

SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.	
3. Address of Operator 205 E. Bender, HOBBS, NM 88240	
4. Well Location Unit Letter <u>F</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>1917</u> Feet From The <u>WEST</u> Line Section <u>30</u> Township <u>24S</u> Range <u>37E</u> NMPM <u>LEA</u> COUNTY	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Request TA Status <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/16/99: MIRU. UNSEAT PUMP. LD RDS & PMP. NUBOP. TIH W/PKR & TBG TO 2820'.
9-17-99: LOAD CSG W/105 BBLS & TEST CSG W/500 PSI. TIH W/CIBP & ATTEMPT TO SET @ 2820'. WOULD NOT SET. TOH & DID NOT HAVE CIBP. TIH W/TBG TO BTM OF CSG @ 2920'. DID NOT TAG PLUG. TIH W/CIBP & SET @ 2820'. CIRC PKR FLUID & ATTEMPT TO TEST.
9-18-99: RUN 30 MIN CHART TEST @ 500 PSI-OK. DUMP 35' CMT ON TOP OF CIBP - PBTD @ 2785'. NDBOP. FLANGE UP WH. RIG DOWN. TEMPORARY ABANDON. {ORIGINAL CHART & COPY OF CHART ATTACHED}

Note to operator: Please use Federal Form 3160-5

*This Approval of Temporary
Abandonment Expires 12/11/2000*

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 11/11/1999
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED BY J. Denise Leake TITLE Engineering Assistant DATE 12/10/99
CONDITIONS OF APPROVAL, IF ANY:

JCBN GWW

OT