## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## MISCELLANEOUS NOTICES

ո ց։ 34

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

		Indicate Nature o	of Notice by Cl	hecking Be	low	
Notice of Intention to Change Plans		Notice of Intent Temporarily Aba			Notice of Intention to Drill Deeper	
Notice of Intention to Plug Well		Notice of Intent to Plug Back	TION	х	Notice of Intention to Set Liner	
Notice of Intention to Squeeze		Notice of Intent to Acidize	TION		Notice of Intention to Shoot (Nitro)	
Notice of Intention to Gun Perforate		Notice of Intent (Other)	ION		Notice of Intention (Other) TREAT VELO	. Y
OIL CONSERVATION COMM SANTA FE, NEW MEXICO	MISSION	M	idland,	Texas	11/8/54	
Gentlemen:			(Place)		(Date)	No.
		certain work as desc			UTHERN CAL FORNIA	
PETROLEUM CORPORA	TION  y or Operator)		Martin	"B"	Well Noin	R
<b>SW</b> 1/4 NW 1/4 of S	ec. 31	T. 245	<sub>R</sub> 37E	NMPM	Langlie-Mattix	(Unit)
Lea	_		, 1	,INIVITIVI.,		Poo
	Coun	ty.				
	FULL	DETAILS OF F	PROPOSED	PLAN OI	F WORK	2 1
	FULL (FOLLOW I	DETAILS OF F INSTRUCTIONS I	PROPOSED IN THE RUL	PLAN OI ES AND R	F WORK EGULATIONS)	
	FULL (FOLLOW I	DETAILS OF FINSTRUCTIONS I	PROPOSED IN THE RUL	PLAN OI ES AND R	F WORK EGULATIONS)	
1. Clean out w	(FOLLOW I	INSTRUCTIONS I	N THE RUL	PLAN OI ES AND R	F WORK LEGULATIONS)	
	(FOLLOW I	T.D. (3517	N THE RUL	ES AND R	EGULATIONS)	A STATE OF THE STA
	(FOLLOW I ell to ! ith Cali	T.D. (3517)	N THE RUL	ES AND R	F WORK EGULATIONS)  DM1te 3470-3490' to	
2. Plug back w shut off wa 3. Run tubing	ell to ! ith Cali ter ent:	T.D. (3517) Seal 3490-3	n the Rul ). 3517' and	es and r	EGULATIONS)	
2. Plug back washut off was 3. Run tubing @ 3370' (5½	ith Caliter ent:	T.D. (3517)  seal 3490-3  ry.  casing to 2  3386).	N THE RUL  1).  3517' and  2500 psi	i Hydro	egulations)  maite 3470-3490' to  min., with packer a	1 12 1
2. Plug back washut off was 3. Run tubing @ 3370' (5½ 4. Make product	ith Caliter ent: & test of shoe of	T.D. (3517) seal 3490-3 ry. casing to 2 3 3386).	n the Rul  1).  3517' and  2500 psi  ect of W.	i Hydrofor 30	egulations)  omite 3470-3490' to	465 ° .
<ol> <li>Plug back washut off washut off was</li> <li>Run tubing a 3370' (5½</li> <li>Make product</li> <li>Dowell Sandsand.</li> </ol>	ith Caliter entite shoe (	T.D. (3517) seal 3490-3 ry. casing to 2 3386). st for effere through	n THE RUL  3517' and  2500 psi  ct of W.  casing,	for 30	egulations)  mite 3470-3490' to  min., with packer a  with the landed @ 34  10,000 gals. oil & 34	465 ° .
2. Plug back washut off was 3. Run tubing @ 3370' (5½ 4. Make product 5. Dowell Sandsand. 6. Run tubing topproved	ith Caliter entracture.	T.D. (3517) seal 3490-3 ry. casing to 2 3 3386). st for efferre through	n THE RUL  1).  3517' and  2500 psi  ect of W.  casing,  producti	i Hydro for 30 S.O. i	egulations)  mite 3470-3490' to  min., with packer a  with the landed @ 34  10,000 gals. oil & 1	465 10,000
2. Plug back washut off was 3. Run tubing @ 3370' (5½ 4. Make product 5. Dowell Sandsand. 6. Run tubing topproved	ith Caliter entracture.	T.D. (3517) seal 3490-3 ry. casing to 2 3 3386). st for efferre through	n THE RUL  1).  3517' and  2500 psi  ect of W.  casing,  producti  SOUTHERN	i Hydro for 30 S.O. i	egulations)  mite 3470-3490' to  min., with packer a  with the landed @ 34  10,000 gals. oil & 34	465 10,000
2. Plug back washut off was 3. Run tubing @ 3370' (5½ 4. Make product 5. Dowell Sandsand. 6. Run tubing topproved	ith Caliter entracture.	T.D. (3517) seal 3490-3 ry. casing to 2 3 3386). st for efferre through	n THE RUL  1).  3517' and  2500 psi  ect of W.  casing,  producti	i Hydrofor 30 S.O. 1 using	egulations)  mite 3470-3490' to  min., with packer in  tith the landed @ 31  10,000 gals. oil & :  OR test.  CORNIA PETROLEUM CORD	465 10,000
<ol> <li>Plug back we shut off wa</li> <li>Run tubing @ 3370' (5½</li> <li>Make product</li> <li>Dowell Sandmand.</li> </ol>	ith Caliter ent: & test of shoe of the sho	T.D. (3517) seal 3490-3 ry. casing to 2 3 3386'). st for effere through	n THE RUL  1).  3517' and  2500 psi  ect of W.  casing,  producti  SOUTHERN	for 30 S.O. 1 Using  CALIF	egulations)  mite 3470-3490' to  min., with packer a  with the landed @ 34  10,000 gals. oil & 1  OR test.	465 10,000
2. Plug back washut off wa  3. Run tubing @ 3370' (5½  4. Make product  5. Dowell Sandand.  6. Run tubing peroved sept as follows:	ith Caliter ent: & test of shoe of the sho	T.D. (3517) seal 3490-3 ry. casing to 2 3 3386). st for efferre through	n THE RUL  1).  3517' and  2500 psi  ect of W.  casing,  producti SOUTHERN  By	for 30 S.O. 1 Using Pet	egulations)  omite 3470-3490' to  min., with packer in  with the landed @ 34  10,000 gals. oil & 10,000 gals	465 10,000