

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-11322 <sup>11323</sup>

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
B-1327

7. Lease Name or Unit Agreement Name  
Langlie Jal Unit

8. Well No. 19

9. Pool name or Wildcat  
Langlie Mattix (SRQ)

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER Injection

2. Name of Operator  
Meridian Oil Inc.

3. Address of Operator  
P.O. Box 51810, Midland, TX 79710

4. Well Location  
Unit Letter L : 1980 Feet From The S Line and 660 Feet From The W Line  
Section 32 Township 24S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3250' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <u>clean out, run injection survey</u> <input checked="" type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU coil tubing unit. RIH with hydroblast tool on 1 1/4" coil tubing. Clean out fill from 3411' to 3617'. POOH with coil tubing and reposition jets to shoot outward. RIH with hydroblast tool on coil tubing and wash casing from 3411' to 3617'. POOH and RDMO coil tubing. Return well to injection. Collect all cleanout water in frac tank and dispose of off lease.
- After injection stabilizes, run injection profile.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donna Williams TITLE Production Assistant DATE 12-4-92

TYPE OR PRINT NAME Donna Williams TELEPHONE NO. 915-688-6943

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

DEC 08 '92