

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate*
(Other instruction: reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

44-LC-032874-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NONE

7. UNIT AGREEMENT NAME

NONE

8. FARM OR LEASE NAME

G. L. Erwin "a"

9. WELL NO.

2

10. FIELD AND POOL, OR WDCAT

Justis Blinebry

11. SEC., T., R., M., OR BLK. ND
SURVEY OR AREA

Sec. 35, T-24-S R-37-E

12. COUNTY OR PARISH 13 STATE
Lea N. M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER

NOV 17 1964

2. NAME OF OPERATOR

TEXACO Inc.

U. S. GEOLOGICAL SURVEY

3. ADDRESS OF OPERATOR

P. O. Box 728 - Hobbs, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surfaceWell located 1650' from the South Line, and 2310' from the
West Line of Section 35, T-24-S, R-37-E, Lea County, New Mexico

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3182' (D. F.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on V well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to open additional perforations in the Justis Blinebry zone as follows:

1. Pull rods and tubing, pump gel down 2 7/8" Casing over old perforations with oil, spot 300 gals acetic acid and lease oil over proposed new perforations.
2. Perforate 2 7/8" Casing with one jet shot at 5446', 5456', 5478', 5502', 5521', 5534', 5541', 5545', 5573', and 5578'. Acidize with 1000 gals regular 15% acid in 10 stages with one ball sealer ahead of each stage. Release pressure and allow balls to drop.
3. Frac with 20,000 gals gelled lease crude oil carrying one pound of sand per gal. (Ball sealers if injection pressure permits).
4. Swab well, recover load oil, Test, return well to production.

18. I hereby certify that the foregoing is true and correct

SIGNED

H. D. Raymond

TITLE

Assistant District Superintendent

DATE November 17, 1964.

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

*See Instructions on Reverse Side

