Form 9-331 (May 1963)

## UTITED STATES DEPARTM . T OF THE INTERIOR (Other instructiverse side)

SUBMIT IN TRY CATE\* on reForm approved. Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO. LC-057509

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

GEOLOGICAL SURVEY

SUNDRY	<b>NOTICES</b>	AND	<b>REPORTS</b>	ON	<b>WELLS</b>
--------	----------------	-----	----------------	----	--------------

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL

NONE

NAME OF OPERATOR

B. FARM OR LHARD NAME

7. UNIT AGREEMENT NAME

TEXACO Inc.

OTHER

G. L Erwin, "b" NCT-2

3. ADDRESS OF OPERATOR P. O. Box 728 - Hobbs, New Mexico 9. WELL NO.

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below.)

10. FIELD AND POOL, OR WILDCAT Justis Blinebry 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Well located 330' from the South Line, and 1650' from the East Line of Section 35, T-24-S, R-37-E, Lea County, N. M.

14. PERMIT NO. Regular

(Other)

WELL X

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

Sec. 35, T-24-S, R-37-E 12. COUNTY OR PARISH | 13. STATE

N. M.

3175' (D. F.)

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

X

REPAIRING WELL

TEST WATER SHUT-OFF FRACTURE TREAT

PULL OR ALTER CASING MULTIPLE COMPLETE

WATER SHUT-OFF FRACTURE TREATMENT

SHOOTING OR ACIDISING

ALTERING CASING ASANDONMENT\*

MHOOT OR ACIDIZE REPAIR WELL

CHANGE PLANS

(Other) (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

We propose to do the following work on subject well:

- 1. Pump gel X-820 temporary blocking material down 2 7/8" Casing, spot oil over perforations 5454 to 5616 . Follow with 500 gals acetic acid.
- 2. Perforate casing with one jet shot at 5406', 5397', 5368', 5354', 5346', 5340', 5326', 5297', 5291', 5280', 5259', 5235', 5224', 5214', and 5202'. Spot acetic acid, and follow with 1500 gals 15% NE acid in 15 equal stages using one ball sealer between stages. Allow balls to drop.
- 3. Frac perforations with 20,000 gals gelled lease crude carrying 20,000 pounds of sand with 1/40 lb. adomite per gallon.
- 4. Swab well, recover load oil, Test, place well on production.

18. I hereby certify that the foregoing is true and correct

SIGNED Raymond D,

Assistant District TITLE

7**,** 1965

(This space for Federal or State office use)

Superintendent

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: TITLE

\*See Instructions on Reverse Side