Form 9-331 (May 1963)

UNI D STATES DEPARTMEN. OF THE INTERIOR (Other instructions verse side) GEOLOGICAL SURVEY

SUBMIT IN TRIPLI ~υE•

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

NA-14218 6. IF INDIAN, ALLOTTEE OR TRIBE NAME

0.10-1					
OTICEC	ANID	DEDODTS	ON	WFII	ς

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

(Do not use this form for programmer (Do not use	LICATION FOR PERMIT—" for such pr	roposals.)			
				7. UNIT AGREEMENT 1	AME
l. OIL GAS CONTRACTOR					
WELL WELL OTHE	R			8. FARM OR LEASE N.	AME
2. NAME OF OPERATOR		I MAL	: 5	C.C. Fristoe	"B" Fed. NCT-
TEXACO Inc				9. WELL NO.	_
3. ADDRESS OF OPERATOR		and all Fill		6	•
P. O. Box	728 Hobbs, New Mexico	88240		10. FIELD AND POOL,	OR WILDCAT
4. LOCATION OF WELL (Report location clearly and in accordance with the See also space 17 below.)			Justis Fusselman North 11. SEC., T., R., M., OR BLE. AND SURVEY OR ARBA		
At surface 660' FEL and 2310 FNL of Sec. 35, T24S, R37E,					
Unit Letter H				Sec. 35, T248	s, R37E
	15. ELEVATIONS (Show whether D	F, RT, GR, etc.)		12. COUNTY OR PARI	SH 13. STATE
14. PERMIT NO.	3178 E			Lea	NM
Regular				·	
16. Check	Appropriate Box To Indicate	Nature of Notice, Rep	oort, or C	other Data	· · · · · · · · · · · · · · · · · · ·

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

••	and a shift of				
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:			
NOTICE OF TEST WATER SHUT-OFF TRACTURE TREAT SHOOT OR ACIDIZE TREAT TREA	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS		WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other)	REPAIRING WELL ALTERING CASING ABANDONMENT®	
(O+b ==)			Completion or Recompletion	n Keport and Dog torm.	
(Other)			details and give pertinent dates, inc	luding estimated date of starti	

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *
 - Pull seating nipple 3 7101'.
 - Perforate 2 7/8 'casing w/1 JSPI @ 7197, 7201, 7211, 7217
 - Spot acid over perforations and acidize perforations 7197-7217 w/1000 gals 20% NEA.
 - Test and return well to production.

18. I hereby certify that the foregoing is true and correct SIGNED	TITLE _	Asst. Dist	t. Supt.	DATE Jan	uary 22,	<u>197</u> 5
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	A	1975	DATE		
*S	ee Instruc	tions on Reverse	Side ALIMUR K. BRUINGIN	EES.		