

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE  
(Other Instructions  
verse side)Form approved,  
Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032592

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

None

7. UNIT AGREEMENT NAME

None

8. FARM OR LEASE NAME

C. C. Fristoe "A" NCT-1

9. WELL NO.

6

10. FIELD AND TOOL, OR WILDCAT

Jalmat Gas

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 35, T-24-S, R-37-E

12. COUNTY OR PARISH 13. STATE

Lea

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

TEXACO Inc.

3. ADDRESS OF OPERATOR

P. O. Box 728, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
(See also space 17 below)  
At surfaceWell is located 660' from the North line and 660' from the  
West Line of Section 35, T-24-S, R-37-E, Unit Letter D, Lea  
County, New Mexico.

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

3195' (D. F.)

10. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Convert to Injection

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

X

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent  
to this work.)\*

TEXACO PROPOSES TO DO THE FOLLOWING WORK ON SUBJECT WELL:

1. Kill Well and Pull Tubing.
2. Drill out Hydromite and Cast Iron Bridge Plug with Sand Line Drill.
3. Run Packer and set @ 3300'.
4. Run 3300' of 2 3/8" od internally plastic coated tubing and latch into packer.
5. Install Flow Controller and begin injection.
6. Well will be converted to water injection on or about December 31, 1968.

18. I hereby certify that the foregoing is true and correct

SIGNED

Assistant District  
Superintendent

DATE December 16, 1968

(This space for Federal or State office use)

APPROVED BY

TITLE

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

DEC 17 1968

\*See Instructions on Reverse Side

J L GORDON  
ACTING DISTRICT ENGINEER