Form 9-331 (May 1963)

FRACTURE TREAT

REPAIR WELL

SHOOT OR ACIDIZE

## UNIT STATES SUBM OEPARTMENT OF THE INTERIOR Verse

SUBMIT IN TRIPLIC (Other instructions o

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

Form approved,
Budget Bureau No. 42-R1424.

ALTERING CASING

ABANDONMENT\*

DEPART	MENT OF THE INTERI GEOLOGICAL SURVEY	OR verse side)	5. LEASE DESIGNATION		
	LC-0325	LC-032579 (E)			
SUNDRY NO (Do not use this form for propuse "APPLIC	6. IF INDIAN, ALLOTTEI	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
OIL GAS GAS WELL OTHER	7. UNIT AGREEMENT NA	7. UNIT AGREEMENT NAME			
2. NAME OF OPERATOR			8. FARM OR LEASE NAME		
National Coop. Refin	Westates Federal				
3. ADDRESS OF OPERATOR			9. WELL NO.		
2215 Wilco Building,	4	4			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			N. Justis Fusselman		
SW/4 NW/4 Section 1,	11. SEC., T., R., M., OR BLK. AND SURVEY OR ARMA				
1980' FNL, 330' FWL	SOMVAT ON ABBA				
·			Sec.1, T-25-S.	R-37-E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF	, RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE	
	3138' KB		Lea	N.Mex	
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data					
NOTICE OF INT	INTION TO:	SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF	PULL OR ALTER CASING XXX	WATER SHUT-OFF	REPAIRING V	VBLL	

(Other)

Perforate

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.)

Westates Federal No. 4 is completed in the Fusselman with perforations 7000'-7006', 7010'-7040'. Present production is approximately 12 BOPD and 80-100 BWPD.

The proposed workover is as follows:

1. Squeeze cement casing leak.

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

- 2. Perforate Fusselman 6932', 34', 36', 44', 46', 71', 73', 75', 77', 79', 81'. (total 11 holes)
- 3. Acidize if necessary and place well back on production.

18. I hereby certiff that the foregoing is true and correct					
SIGNED SIGNED	TITLE	Dist. Prod. Supt. DATE 11-9-73			
(This space for Federal or State office use)  APPROVED BY	тітью	1973 RANK			
CONDITIONS OF APPROVAL, IF ANY:		NOV I BROWN			
CONDITIONS OF APPROVAL, IF ANY:  *See Instructions on Reverse Side Rich Engineer					