• MIDLAND E & P DIVISION

WELL WORK RECOMMENDATIONS Proposals for Well Reconditioning and Subsurface Maintenance Workovers, Expense DD's, PB's, and Conversions

Le	ase:	Humphrey Queen Unit	Well No. 22
Field:		Langlie-Mattix Queen	
		Lea State: New Me	exico
RE	COMMEN	DED PROCEDURE:	
1.	MIRU	cable tool unit - pull producing equipment.	•
2.	Drill P.O.H	deeper from PBD 3365' to new TD of 3500 ft. (135' to	otal) Clean hole.
3.	Run G	R-N log over open hole. Minimum footage.	
4.	Acidi	ze the new open hole section (3365-3500) with 1,500 ga	ls. 15% NE-HC1.
5.	Swab	back acid water and clean up.	
б.	Retur	n well to production.	

RAMeaders/mw 11/19/70 .